

## Existing Building Assessment

### Photos

Attached are photos of the existing facility and conditions:



4817 Existing front elevation (north)



4817 Existing elevation (northeast corner) with HDCP ramp



## Existing Building Assessment



4817 Existing garage and three season porch




4817 Existing garage



## Existing Building Assessment



4817 Front elevation and yard



4817 Fence on east property line



## Existing Building Assessment



4817 East property line and view of Sub-zero parking lot



4817 Southeast elevation of garage

## Existing Building Assessment



4817 North elevation of house



4817 North elevation of garage



## Existing Building Assessment



4817 Southwest corner of house. Evidence observed of wall structure bending



4817 West property line. Pacific Cycle is visible from backyard

## Existing Building Assessment



4817 Roof appears to be in good condition



4817 Existing electrical service. Water damage observed on foundation wall



## Existing Building Assessment



4817 Existing furnace and water heater



4817 Floor joist as visible from basement. Water damage was observed



## Existing Building Assessment



4817 Asbestos floor tile in basement