



Department of Public Works
City Engineering Division

Robert F. Phillips, P.E.
City Engineer

City-County Building, Room 115
210 Martin Luther King, Jr. Boulevard
Madison, Wisconsin 53703
FAX 608 264 9275
www.cityofmadison.com

608 266 4751

Assistant City Engineer
Michael R. Dalley, P.E.

Principal Engineers
Christina M. Bachmann, P.E.
John S. Fahrney, P.E.
Gregory T. Fries, P.E.
Christopher J. Petykowski, P.E.

Facilities & Sustainability
Jeanne E. Hoffman, Manager
James C. Whitney, A.I.A.

Operations Supervisor
Kathleen M. Cryan

GIS Manager
David A. Davis, R.L.S.

Financial Officer
Steven B. Danner-Rivers

Hydrogeologist
Brynn Bemis

NOTICE OF ADDENDUM

ADDENDUM NO. 1

CONTRACT NO. 7069

Proposal Spreadsheet correction

Revise and amend the contract document(s) for the above project as stated in this addendum, otherwise, the original document shall remain in effect.

PROPOSAL PAGE :

REMOVE

Remove PROPOSAL pages E-5

INSERT

Insert PROPOSAL REVISED page E-5


The excel proposal spreadsheet did not list a description of the type of work for bid item number 2. Bid item number 2 should read Topside slab repair below one layer of reinforcing steel. The excel proposal spreadsheet has been corrected to reflect this change.

Please acknowledge this addendum on page E1 of the contract documents.

Electronic version of these documents can be found on the City of Madison web site at:

<http://www.cityofmadison.com/business/PW/contracts/openforBid.cfm>

If you are unable to download plan revisions associated with the addendum, please contact the Engineering office at 608-266-4751 receive the material by another route.


David C. Dryer, P.E., City Traffic Engineer

PROPOSAL
2013 PARKING RAMP MAINTENANCE
CONTRACT # 7069

NAME OF BIDDER

Revised 3/25/13

Item	Type of Work	Est		Unit	
No.		Qty	Unit	Price	Total Bid
1 .	Topside slab repair at unbonded overlay	1,800.00	SF		\$0.00
2 .	Topside slab repair below one layer of reinforcing steel	2,910.00	SF		\$0.00
3 .	Topside slab repair below two layers of reinforcing steel	2,900.00	SF		\$0.00
4 .	Full depth slab replacement	410.00	SF		\$0.00
5 .	Concrete repair at bottom of slab and beams	160.00	SF		\$0.00
6 .	Patch removal area using quickset concrete	350.00	SF		\$0.00
7 .	Concrete repair at vertical surfaces	120.00	SF		\$0.00
8 .	Install supplemental reinforcing steel	600.00	Lbs		\$0.00
9 .	Replace sealant at horizontal and vertical surfaces	4,900.00	LF		\$0.00
10 .	Rout and seal cracks	4,500.00	LF		\$0.00
11 .	Replace sealant at slab edge adjacent to parapet	750.00	LF		\$0.00
12 .	Full System Membrane placement	5,070.00	SF		\$0.00
13 .	Membrane wear coat and top coat placement	87,690.00	SF		\$0.00
14 .	Window frame replacement at SS Co ramp	1.00	EA		\$0.00
15 .	Fabricate and install wire mesh infill panel--West end SSCL ramp	580.00	LF		\$0.00
16 .	Fabricate and install vehicle barrier-level 4 of SSCL ramp	270.00	LF		\$0.00
17 .	Replace grout below spandrel haunches-top level of SS Co ramp	30.00	EA		\$0.00
.	Grand Total				\$0.00