



stress fractures in 2x8 rafters at critical locations

stress fractures in 2x8 rafter at critical locations





existing rafter tails are splitting and decaying. exposed sheathing is beginning to show signs of decay



stress fractures at critical locations on 2x8 rafter. fracture continues down to horizontal tie fasteners

stress fractures at critical locations on 2x8 rafter. horizontal tie failed putting further stress on rafters and exterior walls