


DEMO
PHOTOS



NOTE SETTLING FRONT PORCH, ROTTING TRIM.

SUBJECT PROPERTY


D-10FC



TOP

NARROW, DANGEROUS STAIRWAY AND LANDING,


D- 20F6




TOP

NARROW DANGEROUS WINDING STAIRS.

D-30F6



ANCIENT HEAT DUCTS. (ASBESTOS?)



COBBLED BASEMENT MECHANICAL SYSTEMS,


D-50F6



DETERIORATING FIREPLACE


D-60F6

GENERAL
PHOTOS W/
NEIGHBORING
HOMES,




1501 MORRISON ST.
(HOUSE TO THE EAST ON OTHER
SIDE OF MORRISON PARK.)

◦ SUBJECT PROPERTY IS IN BACKGROUND
ON OTHER SIDE OF THE PARK.



1501 MORRISON ST.


NOTE: • GARAGE IS FORWARD OF HOUSE PROPER.
• SCREEN PORCH IS WELL AHEAD OF THE
HOUSE,



1437 MORRISON ST.
SUBJECT PROPERTY



SUBJECT PROPERTY



LEFT ELEVATION
SUBJECT PROPERTY



NOTE HOW FAR HOUSE IS RAISED
ABOVE GRADE.

SUBJECT PROPERTY

6 OF 13




SOUTH (LAKE) ELEVATION.
SUBJECT PROPERTY

NOTE DETERIORATING SIDING / FASCIA. 7 OF 13




NOTE FLAT ROOFED ADDITION AND JUMP
BALCONY

SUBJECT PROPERTY






1435 MORRISON ST.
(HOUSE TO THE WEST.)



(431 MORRISON ST.
(HOUSE TWO LOTS WEST.)



1427 MORRISON ST, TWO STORY W/ ATTIC LIVING.

13 of 13