

1838 CAMELOT DRIVE



FRONT



BACK (LAKE SIDE)



LEFT SIDE



RIGHT SIDE



L.L. DUCT COMING OUT OF FLOOR - RUST-MOLD CAUSED BY WATER UNDER SLAB



MANY CRACKS - FROM ABNORMAL SETTLING AND SHRINKING



1. Inside window - structure to house door