APPLICATION AND CERTIFICATE FOR PAYMENT CITY OF MADISON ENGINEERING DIVISION

| • | |
|---|---|
| Project Manager: JIM WHITNEY | Page 1 of 4 |
| Project: POLICE DEPARTMENT MIDTOWN DISTRIC | т |
| Contract Number: 7726 | Payment Number: 14 |
| DO NOT WRITE IN THIS BOX - TO BE COMP | LETED BY CITY ENGINEERING PERSONNEL ONLY |
| TOTAL FROM PAGE:4 | 7,706,246.04 |
| LESS RETAINAGE: | 194,627.39 |
| SUBTOTAL: | 7,511,618.65 |
| LESS PREVIOUS PAYMENTS: | 7,277,719.75 |
| CURRENT PAYMENT DUE: | \$ 233,898.90 |
| and that the current payment is now due. | mpleted in accordance with the contract documents, |
| CONTRACTOR: MIRON CONSTRUCTIO | DN CO., INC. DATE |
| NSPECTOR'S CERTIFICATE FOR PAYMENT: The undersigned Inspector certifies that to th by this application for payment has been con and that the contractor is entitled to payment | ne best of his/her knowledge, the work covered npleted in accordance with the contract documents, t for the amount certified. |
| 1. Millitnen INSPECTOR | |
| PLEASE PROVIDE THE TIME PERIOD FOR THIS PAYMENT | |
| PLEASE PROVIDE THE CONTRACTOR/SUBCONTRACTORS | TO: 10.31.2018 |
| Best Mechanical | Monona Plumbing |
| Forward Electric | |
| Miron Construction | |

NOTE:

.

: SIGNED PAYMENT REQUEST SHALL BE SUBMITTED TO THE ENGINEER/INSPECTOR. PARTIAL PAYMENTS CAN BE PROCESSED EVERY TWO WEEKS.

.

RETAINAGE IS ONLY 5% OF TOTAL WORK COMPLETED UNTIL 50% OF THE WORK IS DONE AND THEN RETAINAGE IS 2.5% OF THE TOTAL CONTRACT DOLLARS (COLUMN #4)!!!! ACCOUNT NO. 10390-31-140

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

| MIRON CONSTRUCTION CO., INC. | |
|------------------------------------|--|
| POLICE DEPARTMENT MIDTOWN DISTRICT | |
| CONTRACT NO. 7726 | |
| PAYMENT NO. 14 | |
| | |

| PAYMENT | NU. 14 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | #10 | 11 | 12 |
|----------|--|-------------------------|----------|-------------------|---------------------|---------------------------|---------------------|------------------|-------------------------|---------------------------|----------------|---------------------------|---------------------|
| ITEM | TYPE OF WORK | ESTIMATED QUANTITIES | UNITS | UNIT PRICE BID | CONTRACT DOLLARS | C. O. DOLLARS | UNITS THIS APPL. | EXTENSION | UNITS PREV. APPL.(S) | EXTENSION | TOTAL UNITS | EXTENSION | PERCENT COMPLETE |
| CCOUNT | NO. 10390-31-140 | | | | | | | | | | | | |
| 90001 E | lase Bid | 1.00 | Lump Sum | \$7,518,738.00 | \$7,518,738.00 | | 0.03 | \$191,999.00 | 0.96 | \$7,243,220.58 | 0.99 | \$7,435,219.58 | 98.9% |
| ONTRAC | T TOTALS | | | | \$7,518,738.00 | | | \$191,999.00 | | \$7,243,220.58 | | \$7,435,219.58 | 98.89% |
| CHANGE C | DRDER #1, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| - | COR-1 EXTRA DEMO | 1.00 | Lump Sum | \$5,991.23 | | \$5,991.23 | 0.00 | \$0.00 | 1.00 | \$5,991.23 | 1.00 | \$5,991.23 | 100.0% |
| | COR-2 UPGRADED BALL VALVES | 1.00 | Lump Sum | \$1,800.33 | | \$1,800.33 | 0.00 | \$0.00 | 1.00 | \$1,800.33 | 1.00 | \$1,800.33 | 100.0% |
| | COR-5 DELETE IRRIGATION | 1.00 | Lump Sum | -\$22,266.46 | | (\$22,266.46) | 0.00 | \$0.00 | 1.00 | (\$22,266.46) | 1.00 | (\$22,266.46) | |
| | COR-6 REMOVE WESTMORLAND COR-7 DOOR CHANGES | 1.00 1.00 | Lump Sum | -\$3,662.26 | | (\$3,662.26) | 0.00 0.00 | \$0.00 | 1.00 1.00 | (\$3,662.26) | 1.00 1.00 | (\$3,662.26) | 100.0% 100.0% |
| | COR-7 DOOR CHANGES | 1.00 | Lump Sum | \$1,402.79 | | \$1,402.79 | | \$0.00 | | \$1,402.79 | 1.00 | \$1,402.79 | |
| | HANGES | 1.00 | Lump Sum | \$8,704.91 | | \$8,704.91 | 0.00 | \$0.00 | 1.00 | \$8,704.91 | 1.00 | \$8,704.91 | 100.0% |
| - | COR-9 UNDERCUTTING FOR FOOTING | 1.00 | Lump Sum | \$2,793.94 | | \$2,793.94 | 0.00 | \$0.00 | 1.00 | \$2,793.94 | 1.00 | \$2,793.94 | 100.0% |
| | COR-10 A/E REVISIONS | 1.00 | Lump Sum | \$3,823.54 | | \$3,823.54 | 0.00 | \$0.00 | 1.00 | \$3,823.54 | 1.00 | \$3,823.54 | 100.0% |
| | COR-11 COUNTERTOP ADJUSTMENTS | 1.00 | Lump Sum | \$1,039.54 | | \$1,039.54 | 0.00 | \$0.00 | 1.00 | \$1,039.54 | 1.00 | \$1,039.54 | 100.0% |
| C | HANGE ORDER #1 TOTAL | | | | | (\$372.44) | | \$0.00 | | (\$372.44) | | (\$372.44) | |
| HANGE C | ORDER #2, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| S | COR-12 Changes to the 54" Storm wer on Midtown PD Site COR-13 Changes to ADA operator, | 1.00 | Lump Sum | -\$1,988.81 | | (\$1,988.81) | 0.00 | \$0.00 | 1.00 | (\$1,988.81) | 1.00 | (\$1,988.81) | 100.0% |
| a | buver opening, landscaping at flag pole, ddition of a gate in the fence and some tructural steel additions | 1.00 | Lump Sum | \$8,046.97 | | \$8,046.97 | 0.00 | \$0.00 | 1.00 | \$8,046.97 | 1.00 | \$8,046.97 | 100.0% |
| d | COR-14 Changes to flushable floor rains in holding area (QTY 2) and hanges to shower enclosures | 1.00 | Lump Sum | \$2,648.45 | | \$2,648.45 | 0.00 | \$0.00 | 1.00 | \$2,648.45 | 1.00 | \$2,648.45 | 100.0% |
| | COR-15 Addition of coverboard under oof section that will have PV panels | 1.00 | Lump Sum | \$10,453.50 | | \$10,453.50 | 0.00 | \$0.00 | 1.00 | \$10,453.50 | 1.00 | \$10,453.50 | 100.0% |
| c | HANGE ORDER #2 TOTAL | | | | | \$19,160.11 | | \$0.00 | | \$19,160.11 | | \$19,160.11 | - |
| HANGE (| ORDER #3, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| - | COR-16 Undercutting | 1.00 | Lump Sum | \$1,021.06 | | \$1,021.06 | 0.00 | \$0.00 | 1.00 | \$1,021.06 | 1.00 | \$1,021.06 | 100.0% |
| | COR-17 Removal of Old Foundation - | 1.00 | Lump Sum | \$6,168.62 | | \$6,168.62 | 0.00 | \$0.00 | 1.00 | \$6,168.62 | 1.00 | \$6,168.62 | 100.0% |
| | nforseen | | • | | | . , | | | | . , | | | |
| | COR-18 Changes to Capstone Style HANGE ORDER #3 TOTAL | 1.00 | Lump Sum | \$3,391.58 | | \$3,391.58 \$10,581.26 | 0.00 | \$0.00 \$0.00 | 1.00 | \$3,391.58 \$10,581.26 | 1.00 | \$3,391.58 \$10,581.26 | 100.0% |
| | ORDER #4, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| | COR-19 Electrical and Tech changes to | | | | 1 | I | l | | 1 | 1 | | | 1 |
| lı F | ncident, Briefing and Community | 1.00 | Lump Sum | \$21,409.72 | | \$21,409.72 | 0.00 | \$0.00 | 1.00 | \$21,409.72 | 1.00 | \$21,409.72 | 100.0% |
| | COR-20 Extra Windshield Tags for | 1.00 | Lump Sum | \$1,163.61 | | \$1,163.61 | 0.00 | \$0.00 | 1.00 | \$1,163.61 | 1.00 | \$1,163.61 | 100.0% |
| | quads to open garage doors | 1.00 | • | | | - | 0.00 | | | | | | |
| - | COR-21 Safety Railing for Roof Hatch | 1.00 | Lump Sum | \$1,672.56 | | \$1,672.56 | 0.00 | \$0.00 | 1.00 | \$1,672.56 | 1.00 | \$1,672.56 | 100.0% |

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

MIRON CONSTRUCTION CO., INC. POLICE DEPARTMENT MIDTOWN DISTRICT

| PATIVIEN | IT NO. 14 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | ********* #10 | 11 | 12 |
|----------|--|-------------------------|----------|-------------------|---------------------|----------------------------|---------------------|-----------------------|-------------------------|----------------------------|------------------|--------------------------|---------------------|
| ITEM | TYPE OF WORK | ESTIMATED QUANTITIES | UNITS | UNIT PRICE BID | CONTRACT DOLLARS | C. O. DOLLARS | UNITS THIS APPL. | EXTENSION | UNITS PREV. APPL.(S) | EXTENSION | TOTAL UNITS | EXTENSION | PERCENT COMPLETE |
| | - COR-22 Modifications to Window Head/Jamb Detail | 1.00 | Lump Sum | \$905.73 | | \$905.73 | 0.00 | \$0.00 | 1.00 | \$905.73 | 1.00 | \$905.73 | 100.0% |
| | - COR-23 Revised sink at Breakroom 116 | 1.00 | Lump Sum | \$191.11 | | \$191.11 | 0.00 | \$0.00 | 1.00 | \$191.11 | 1.00 | \$191.11 | 100.0% |
| | - COR-24 CB#8/ASI-6 Floor finish changes and other minor changes CHANGE ORDER #4 TOTAL | 1.00 | Lump Sum | \$11,758.60 | | \$11,758.60 \$37,101.33 | 0.00 | \$0.00 \$0.00 | 1.00 | \$11,758.60 \$37,101.33 | 1.00 | \$11,758.60 | 100.0% |
| CHANGE | E ORDER #5, ACC'T NO. 10390-31-140 | | | | | | | •••• | | , | | , | |
| | - COR-25 Retaining Wall and Plywood | 1.00 | Lump Sum | \$22,356.63 | | \$22,356.63 | 0.00 | \$0.00 | 1.00 | \$22,356.63 | 1.00 | \$22,356.63 | 100.0% |
| | - COR-26 Audio Video Equipment and Install | 1.00 | Lump Sum | \$65,826.12 | | \$65,826.12 | 0.00 | \$0.00 | 1.00 | \$65,826.12 | 1.00 | \$65,826.12 | 100.0% |
| | - COR-27 Driveway and Parking Lot Undercutting | 1.00 | Lump Sum | \$8,550.14 | | \$8,550.14 | 0.00 | \$0.00 | 1.00 | \$8,550.14 | 1.00 | \$8,550.14 | 100.0% |
| | - COR-28 Cutting and Patching of Floor for A/V Changes | 1.00 | Lump Sum | \$1,661.10 | | \$1,661.10 | 0.00 | \$0.00 | 1.00 | \$1,661.10 | 1.00 | \$1,661.10 | 100.0% |
| | - COR-29 Base Mount Exterior Light Fixtures instead of Direct Bury | 1.00 | Lump Sum | \$2,138.22 | | \$2,138.22 | 0.96 | \$2,061.51 | 0.02 | \$38.22 | 0.98 | \$2,099.73 | 98.2% |
| | CHANGE ORDER #5 TOTAL | | | | | \$100,532.21 | | \$2,061.51 | J _ | \$98,432.21 | ı <u> </u> | \$100,493.72 | 99.96% |
| CHANGE | E ORDER #6, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| | - COR-30 Storm Pipe Reconfiguration | 1.00 | Lump Sum | \$8,138.95 | | \$8,138.95 | 0.00 | \$0.00 | 1.00 | \$8,138.95 | 1.00 | \$8,138.95 | 100.0% |
| | - COR-31 Added Labor by IBS to install 24 WAP's | 1.00 | Lump Sum | \$1,130.88 | | \$1,130.88 | 0.00 | \$0.00 | 1.00 | \$1,130.88 | 1.00 | \$1,130.88 | 100.0% |
| | CHANGE ORDER #6 TOTAL | | | | | \$9,269.83 | · · · · | \$0.00 | | \$9,269.83 | · · | \$9,269.83 | - |
| CHANGE | E ORDER #7, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| | - COR-32 Addition of Ladder in elevator shaft above cab to allow access to duct smoke detector at top of shaft | 1.00 | Lump Sum | \$1,089.86 | | \$1,089.86 | 0.00 | \$0.00 | 1.00 | \$1,089.86 | 1.00 | \$1,089.86 | 100.0% |
| | - COR-33 Changed door hardware on door B001-1 to a delayed access hardware based on Fire Department review | 1.00 | Lump Sum | \$1,886.93 | | \$1,886.93 | 0.00 | \$0.00 | 1.00 | \$1,886.93 | 1.00 | \$1,886.93 | 100.0% |
| | - COR-34 Time and Material work related to rerouting some piping and additional shrouds to avoid structural elements | 1.00 | Lump Sum | \$3,437.18 | | \$3,437.18 | 0.00 | \$0.00 | 1.00 | \$3,437.18 | 1.00 | \$3,437.18 | 100.0% |
| | CHANGE ORDER #7 TOTAL | | | | | \$6,413.97 | | \$0.00 | | \$6,413.97 | · · | \$6,413.97 | - |
| CHANGE | E ORDER #8, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| | - COR-35 Shower compartments | 1.00 | Lump Sum | \$1,503.12 | | \$1,503.12 | 0.00 | \$0.00 | 1.00 | \$1,503.12 | 1.00 | \$1,503.12 | 100.0% |
| | - COR-36 Two new breakroom cabinets | 1.00 | Lump Sum | \$1,571.86 | | \$1,571.86 | 0.00 | \$0.00 | 1.00 | \$1,571.86 | 1.00 | \$1,571.86 | 100.0% |
| | - COR-37 Display mounts in Room 108 - COR-39 Addition of concrete | 1.00 | Lump Sum | \$388.57 | | \$388.57 | 0.57 | \$220.01 | 0.22 | \$84.24 | 0.78 | \$304.25 | 78.3% |
| | - COR-39 Addition of concrete motorcycle parking area CHANGE ORDER #8 TOTAL | 1.00 | Lump Sum | \$1,724.93 | | \$1,724.93 \$5,188.48 | 0.00 | \$0.00 \$220.01 | 1.00 | \$1,724.93 \$4,884.15 | 1.00 | \$1,724.93 \$5,104.16 | 100.0% 98.37% |
| | | | | | | <i>40,100.40</i> | | <i><i><i></i></i></i> | | ¥4,004.10 | | ψ0,104.10 | 00.0770 |
| CHANGE | ORDER #9, ACC'T NO. 10390-31-140 | 1.00 | Lump Sum | \$34,959.04 | | \$34,959.04 | | \$0.00 | 1.00 | | | | |

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

MIRON CONSTRUCTION CO., INC. POLICE DEPARTMENT MIDTOWN DISTRICT CONTRACT NO. 7726

| | ACT NO. 7726 NT NO. 14 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | ******** #10 | 11 | 12 |
|-------|--|-------------------------|----------------------|--------------------------|---------------------|---------------------------|---------------------|---------------------------|-------------------------|-----------------------|-----------------|---------------------------|---------------------|
| ITEM | TYPE OF WORK | ESTIMATED QUANTITIES | UNITS | UNIT PRICE BID | CONTRACT DOLLARS | C. O. DOLLARS | UNITS THIS APPL. | EXTENSION | UNITS PREV. APPL.(S) | EXTENSION | TOTAL UNITS | EXTENSION | PERCENT COMPLETE |
| | - COR-40 Replacement flat manhole cover | 1.00 | Lump Sum | \$184.78 | | \$184.78 | 0.00 | \$0.00 | 1.00 | \$184.78 | 1.00 | \$184.78 | 100.0% |
| | - COR-41 Moisture mitigation | 1.00 | Lump Sum | \$23,060.00 | | \$23,060.00 | 0.56 | \$12,906.71 | 0.22 | \$5,080.09 | 0.78 | \$17,986.80 | 78.0% |
| | - COR-42 Solar panel support modification | 1.00 | Lump Sum | \$3,432.23 | | \$3,432.23 | 0.00 | \$0.00 | 1.00 | \$3,432.23 | 1.00 | \$3,432.23 | 100.0% |
| | - COR-43 Fencing modifciations CHANGE ORDER #9 TOTAL | 1.00 | Lump Sum | \$6,805.33 | | \$6,805.33 \$68,441.38 | 1.00 | \$6,805.33 \$19,712.04 | 0.00 | \$0.00 \$43,656.14 | 1.00 | \$6,805.33 \$63,368.18 | 100.0% 92.59% |
| CHANG | E ORDER #10, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| | - COR-44 Modify the break room casework to accomodate the donated Sub Zero refrigerators | 1.00 | Lump Sum | \$3,976.09 | | \$3,976.09 | 1.00 | \$3,976.09 | 0.00 | \$0.00 | 1.00 | \$3,976.09 | 100.0% |
| | COR-45 Add a data jack for a multifunction copier | 1.00 | Lump Sum | \$294.60 | | \$294.60 | 1.00 | \$294.60 | 0.00 | \$0.00 | 1.00 | \$294.60 | 100.0% |
| | - COR-46 Undo COR-36 that is unneeded for ladder access in the elevator shaft | 1.00 | Lump Sum | -\$1,089.86 | | (\$1,089.86) | 1.00 | (\$1,089.86) | 0.00 | \$0.00 | 1.00 | (\$1,089.86) | 100.0% |
| | - COR-47 Add shower seats to the bathroom | 1.00 | Lump Sum | \$1,015.34 | | \$1,015.34 | 1.00 | \$1,015.34 | 0.00 | \$0.00 | 1.00 | \$1,015.34 | 100.0% |
| | - COR-48 Remove old foundation at the bio-retention basin location | 1.00 | Lump Sum | \$4,237.47 | | \$4,237.47 | 1.00 | \$4,237.47 | 0.00 | \$0.00 | 1.00 | \$4,237.47 | 100.0% |
| | - COR-49 Add signs to bathroom and elevator equipment room | 1.00 | Lump Sum | \$152.23 | | \$152.23 | 1.00 | \$152.23 | 0.00 | \$0.00 | 1.00 | \$152.23 | 100.0% |
| | COR-50 Modify a sink to be ADA accessible | 1.00 | Lump Sum | \$152.93 | | \$152.93 | 1.00 | \$152.93 | 0.00 | \$0.00 | 1.00 | \$152.93 | 100.0% |
| | - COR-51 Add data outlets in rooms 137 and 138 for interview cameras | 1.00 | Lump Sum | \$1,085.47 | | \$1,085.47 | 1.00 | \$1,085.47 | 0.00 | \$0.00 | 1.00 | \$1,085.47 | 100.0% |
| | - COR-52 Add additional corner guards requested by MPD after move in. Guards to be installed by MPD Staff. | 1.00 | Lump Sum | \$217.04 | | \$217.04 | 1.00 | \$217.04 | 0.00 | \$0.00 | 1.00 | \$217.04 | 100.0% |
| | CHANGE ORDER #10 TOTAL | | | | | \$10,041.31 | - | \$10,041.31 | J _ | \$0.00 | J . | \$10,041.31 | 1 |
| CHANG | E ORDER #11, ACC'T NO. 10390-31-140 | | | | | | | | | | | | |
| | - COR-53 Radiator shrouds | 1.00 | Lump Sum | \$1,348.79 | | \$1,348.79 | 1.00 | \$1,348.79 | 0.00 | \$0.00 | 1.00 | \$1,348.79 | 100.0% |
| | - COR-54 Elevator work due to Bi | 1.00 | Lump Sum | \$6,612.60 | | \$6,612.60 | 1.00 | \$6,612.60 | 0.00 | \$0.00 | 1.00 | \$6,612.60 | 100.0% |
| | - COR-55 Credit for fence staining | 1.00 | Lump Sum | -\$1,519.68 | | (\$1,519.68) | 1.00 | (\$1,519.68) | | \$0.00 | 1.00 | (\$1,519.68) | 100.0% |
| | - COR-56 Electrical work (power) | 1.00 | Lump Sum | \$512.68 | | \$512.68 | 1.00 | \$512.68 | 0.00 | \$0.00 | 1.00 | \$512.68 | 100.0% |
| | - COR-57 Electrical work (switches) - COR-58 HDMI connection Briefing | 1.00 1.00 | Lump Sum Lump Sum | \$1,335.40 \$1,575.24 | | \$1,335.40 \$1,575.24 | 1.00 1.00 | \$1,335.40 \$1,575.24 | 0.00 0.00 | \$0.00 \$0.00 | 1.00 1.00 | \$1,335.40 \$1,575.24 | 100.0% 100.0% |
| | Room | 1.00 | Lump Sum | ψ1,07J.24 | | | 1.00 | | 0.00 | | 1.00 | | 100.0% |
| | CHANGE ORDER #11 TOTAL | | | | | \$9,865.03 | | \$9,865.03 | | \$0.00 | | \$9,865.03 | |
| GRAND | TOTALS (CONTRACT TOTALS PLUS CHAN | IGE ORDERS) | | | \$7,794,960.47 | | • | \$233,898.90 | • | \$7,472,347.14 | • • | \$7,706,246.04 | - 98.86% |