# APPLICATION AND CERTIFICATE FOR PAYMENT CITY OF MADISON ENGINEERING DIVISION

Project Manager:	MIKE SCHUCHARDT		Page 1 of5
	N MUNICIPAL BUILDING RENOVATION		
Contract Number:	7939	Paymen	nt Number: 13
DO NOT WRITE	IN THIS BOX - TO BE COMPLETED	BY CITY ENGINEERING PE	RSONNEL ONLY
TOTAL FROM PAGE:	5	20,631,6	80.10
LESS RETAINAGE:		529,19	
SUBTOTAL:		70,102,49	
LESS PREVIOUS PAY	MENTS:	19,427,63	36.10
CURRENT PAYMENT	DUE:	\$ 674,859	1.65
by this ap	rsigned contractor certifies that to the best plication for payment has been completed the current payment is now due.  CTOR: J. P. CULLEN & SONS, INC.	d in accordance with the co	9/19/18 DATE
INSPECTOR'S CERTII The under by this ap and that the	FICATE FOR PAYMENT: rsigned Inspector certifies that to the best plication for payment has been completed the contractor is entitled to payment for the	of his/her knowledge, the	work covered
PLEASE PROVIDE THE (	CONTRACTOR/SUBCONTRACTORS THAT ughes, Hooper, Wall-Te	TO:	:6/30/18 :9/30/18 URING THIS PERIOD:
	AYMENT REQUEST SHALL BE SUBMITTED		CTOR.

J. P. CULLEN & SONS, INC.
MADISON MUNICIPAL BUILDING RENOVATION
CONTRACT NO. 7939
PAYMENT NO. 13

	NT NO. 13	1	2	3	4	5	6	7	8	9	****** #10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
ACCOU	NT NO. 10129-401-140												
90000	MADISON MUNICIPAL BUILDING - RENOVATION (EXCLUDING ALTERNATES 1 AND 2)	1.00	LUMP SUM	\$18,203,174.00	\$18,203,174.00		0.02	\$351,845.99	0.96	\$17,518,327.81	0.98	\$17,870,173.81	98.2%
Alternat	re No. 1:												
90001	PROVIDE ALL WORK TO INSTALL WINDOW TYPES W1, W5, W5a, W6, W7 AS INDICATED ON SHEETS A201, A202, A620, A622, A653; AND AS SPECIFIED IN EXHIBIT "N" SPECIFICATION SECTION 085113 ALUMINUM WINDOWS.	1.00	LUMP SUM	\$376,172.00	\$376,172.00		0.00	\$0.00	1.00	\$376,172.00	1.00	\$376,172.00	100.0%
Alternat	e No. 2:												
90002	PROVIDE ALL WORK TO INSTALL AN EXTENSIVE VEGETATED ROOF MODULE (TRAY) TO ROOF AREAS AS INDICATED ON SHEET C110 AND RELATED DETAILS; AND AS SPECIFIED IN EXHIBIT "N" SPECIFICATION SECTIONS 075213 APP MODIFIED ASPHALT BITUMINOUS ROOFING OR 075216 SBS MODIFIED ASHPALT BITUMINOUS ROOFING.	1.00	LUMP SUM	\$125,968.00	\$125,968.00		1.00	\$125,968.00	0.00	\$0.00	1.00	\$125,968.00	100.0%
CONTRA	ACT TOTALS				\$18,705,314.00		=	\$477,813.99	= =	\$17,894,499.81	=	\$18,372,313.81	98.22%
CHANG	E ORDER #1, ACC'T NO. 10129-401-140 - COR-1 Add cost of builders risk insurance	1.00	LUMP SUM	\$16,794.13		\$16,794.13	0.00	\$0.00	1.00	\$16,794.13	1.00	\$16,794.13	100.0%
CHANG	E ORDER #2, ACC'T NO. 10129-401-140												
	- COR-2 CB-1 Brick tuckpointing and masonry repairs on 2nd and 3rd floor walls facing S. Pinckney St.	1.00	LUMP SUM	\$509,749.83		\$509,749.83	0.00	\$0.00	1.00	\$509,749.83	1.00	\$509,749.83	100.0%
CHANG	E ORDER #3, ACC'T NO. 10129-401-140												
	- COR-3 Addition to transformer vault	1.00	LUMP SUM	\$90,829.00		\$90,829.00	0.00	\$0.00	1.00	\$90,829.00	1.00	\$90,829.00	100.0%
CHANG	COR-5 Hooper plumbing changes     COR-6 ECI power to cameras     COR-7 NAMI add smoke dampers     COR-8 Elec room slab replacement	1.00 1.00 1.00 1.00	LUMP SUM LUMP SUM LUMP SUM LUMP SUM	\$8,187.41 \$2,447.73 \$5,212.35 \$2,607.57		\$8,187.41 \$2,447.73 \$5,212.35 \$2,607.57	0.00 0.00 0.00 0.00	\$0.00 \$0.00 \$0.00 \$0.00	1.00 1.00 1.00	\$8,187.41 \$2,447.73 \$5,212.35 \$2,607.57	1.00 1.00 1.00	\$8,187.41 \$2,447.73 \$5,212.35 \$2,607.57	100.0% 100.0% 100.0% 100.0%
	- COR-9 NAMI provided FDI attic stock	1.00	LUMP SUM	\$435.56		\$435.56	0.00	\$0.00	1.00	\$435.56	1.00	\$435.56	100.0%
	- COR-10 Cullen Historic door relocation	1.00	LUMP SUM	\$3,892.19		\$3,892.19	0.00	\$0.00	1.00	\$3,892.19	1.00	\$3,892.19	100.0%

J. P. CULLEN & SONS, INC. MADISON MUNICIPAL BUILDING RENOVATION CONTRACT NO. 7939 PAYMENT NO. 13

	ACT NO. 7939 NT NO. 13					İ	Ī		ı		******		I
	NT NO. 13	1	2	3	4	5	6	7	8	9	#10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
	- COR-11 Duct relocation due to structural conflict	1.00	LUMP SUM	\$1,682.13		\$1,682.13	0.00	\$0.00	1.00	\$1,682.13	1.00	\$1,682.13	100.0%
	- COR-4 CB-2 Exterior Window Rehabilitation	1.00	LUMP SUM	\$433,084.00		\$433,084.00	0.11	\$48,084.00	0.89	\$385,000.00	1.00	\$433,084.00	100.0%
	CHANGE ORDER #4 TOTAL					\$457,548.94		\$48,084.00		\$409,464.94		\$457,548.94	
CHANG	E ORDER #5, ACC'T NO. 10129-401-140												
	- COR-15 CB-7 Revision to ductwork on 3rd floor	1.00	LUMP SUM	\$13,166.54		\$13,166.54	0.00	\$0.00	1.00	\$13,166.54	1.00	\$13,166.54	100.0%
CHANG	E ORDER #6, ACC'T NO. 10129-401-140												
	- COR-13 Ground level perimeter interior wall replacement	1.00	LUMP SUM	\$9,738.02		\$9,738.02	0.00	\$0.00	1.00	\$9,738.02	1.00	\$9,738.02	100.0%
	- COR-14 Concrete topping removal on 3rd floor for mechanical room	1.00	LUMP SUM	\$28,176.83		\$28,176.83	0.00	\$0.00	1.00	\$28,176.83	1.00	\$28,176.83	100.0%
	- COR-16 CB-4 Masonry chimney repairs	1.00	LUMP SUM	\$20,020.78		\$20,020.78	0.00	\$0.00	1.00	\$20,020.78	1.00	\$20,020.78	100.0%
	-COR-17 Credit for unused masonry tuck pointing winter conditions (CO-2)	1.00	LUMP SUM	-\$58,075.00		(\$58,075.00)	0.00	\$0.00	1.00	(\$58,075.00)	1.00	(\$58,075.00)	100.0%
	- COR-18 CB-9 Furnish and install 73 fire dampers for ductwork system	1.00	LUMP SUM	\$60,634.48		\$60,634.48	0.00	\$0.00	1.00	\$60,634.48	1.00	\$60,634.48	100.0%
	- COR-20 Historic plaster repairs	1.00	LUMP SUM	\$49,474.09		\$49,474.09	0.00	\$0.00	1.00	\$49,474.09	1.00	\$49,474.09	100.0%
	- COR-21 Misc additional walls on 2nd & 3rd floors	1.00	LUMP SUM	\$37,102.96		\$37,102.96	0.00	\$0.00	1.00	\$37,102.96	1.00	\$37,102.96	100.0%
	CHANGE ORDER #6 TOTAL					\$147,072.16		\$0.00	-	\$147,072.16		\$147,072.16	_
CHANG	E ORDER #7, ACC'T NO. 10129-401-140												
	- COR-12 Mech Rm insulation	1.00	LUMP SUM	\$9,908.76		\$9,908.76	0.00	\$0.00	1.00	\$9,908.76	1.00	\$9,908.76	100.0%
	- COR-23 Glass replacements in existing windows	1.00	LUMP SUM	\$38,171.54		\$38,171.54	0.00	\$0.00	1.00	\$38,171.54	1.00	\$38,171.54	100.0%
	- COR-24 CB-5 Layout revisons to Rm 108 & 152	1.00	LUMP SUM	\$16,029.86		\$16,029.86	0.00	\$0.00	1.00	\$16,029.86	1.00	\$16,029.86	100.0%
	- COR-26 Add underlayment due to flooring removal of asbestos adhesive	1.00	LUMP SUM	\$15,082.08		\$15,082.08	0.00	\$0.00	1.00	\$15,082.08	1.00	\$15,082.08	100.0%
	- COR-28 Demo and remove concrete mezzanine at North wall 261	1.00	LUMP SUM	\$4,781.90		\$4,781.90	0.00	\$0.00	1.00	\$4,781.90	1.00	\$4,781.90	100.0%
	- COR-29 Miscellaneous demo of unforeseen walls and ceilings on levels	1.00	LUMP SUM	\$7,439.41		\$7,439.41	0.00	\$0.00	1.00	\$7,439.41	1.00	\$7,439.41	100.0%
	1 & 2 CHANGE ORDER #7 TOTAL					\$91,413.55	l .	\$0.00	J .	\$91,413.55		\$91,413.55	
CHVNG	E ORDER #8, ACC'T NO. 10129-401-140												
CHANG	- COR-30 Interior wall framing on 2nd and 3rd floors	1.00	LUMP SUM	\$29,360.40		\$29,360.40	0.00	\$0.00	1.00	\$29,360.40	1.00	\$29,360.40	100.0%
	- COR-34 Historic plaster repair 2nd	1.00	LUMP SUM	\$40,667.60		\$40,667.60	0.00	\$0.00	1.00	\$40,667.60	1.00	\$40,667.60	100.0%
	floor CHANGE ORDER #8 TOTAL					\$70,028.00	l .	\$0.00		\$70,028.00		\$70,028.00	

CHANGE ORDER #9, ACC'T NO. 10129-401-140

J. P. CULLEN & SONS, INC.
MADISON MUNICIPAL BUILDING RENOVATION
CONTRACT NO. 7939
PAYMENT NO. 13

TEM TYPE OF WORK QUANTITIES UNITS BID DOLLARS DOLLARS APPL EXTENSION APPL(S) EXTENSION UNITS EXTENSION CO-COR-31 Added will framing 12nd floor 1.00 LUMP SUM \$48,582.03 \$48,582.03 \$0.00 \$0.00 \$0.00 \$1.00 \$48,582.03 \$1.00 \$48,582.03 \$24,434.00 \$0.00 \$0.00 \$0.00 \$1.00 \$324,434.00 \$24,434.00 \$0.00 \$0.00 \$0.00 \$1.00 \$324,434.00 \$24,434.00 \$0.00 \$0.00 \$0.00 \$1.00 \$324,434.00 \$24,434.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$0.00 \$0.00 \$1.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$1.00 \$324,434.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$1.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$0.00 \$324,434.00 \$		ACT NO. 7939 NT NO. 13								1		*****		ĺ
TEM TYPE OF WORK QUANTITIES UNITS BID DOLLARS DOLLARS APPL EXTENSION APPL(S) EXTENSION UNITS EXTENSION COLOR-12 COR-31 Added wall framing 2nd floor 1.00 LUMP SUM \$48,582.03 \$48,582.03 \$0.00 \$0.00 \$0.00 \$0.00 \$1.00 \$48,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$548,582.03 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.			1	2	3	4	5	6	7	8	9	#10	11	12
- COR-35 Added roal framing 1st, ground floor ground floo	ITEM	TYPE OF WORK		UNITS					EXTENSION		EXTENSION		EXTENSION	PERCENT COMPLETE
ground floor - COR-54 Additional Saturday premium time to maintain schedule - COR-54 Additional Saturday premium time to maintain schedule - COR-54 Added plaster work on 1st 1.00		- COR-31 Added wall framing 2nd floor	1.00	LUMP SUM	\$48,582.03		\$48,582.03	0.00	\$0.00	1.00	\$48,582.03	1.00	\$48,582.03	100.0%
time to maintain schedule 1.00			1.00	LUMP SUM	\$24,434.00		\$24,434.00	0.00	\$0.00	1.00	\$24,434.00	1.00	\$24,434.00	100.0%
## 1000 ## 1.00 LUMP SUM \$19,99.87 \$19,99.87 \$19,99.87 \$19,99.87 \$19,99.87 \$10.00 \$30.00 \$1.00 \$15,000.00 \$0.85 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.00 \$17,000.0			1.00	LUMP SUM	\$11,604.55		\$11,604.55	0.00	\$0.00	1.00	\$11,604.55	1.00	\$11,604.55	100.0%
- COR-41 CB-10 Interior finishes CHANGE ORDER #3 OCT NO. 10129-401-140 - COR-42 CB-10 Lighting inverter and lighting inverter and ground levels - COR-43 CM of the control			1.00	LUMP SUM	\$58,709.18		\$58,709.18	0.00	\$0.00	1.00	\$58,709.18	1.00	\$58,709.18	100.0%
CHANGE ORDER #9 TOTAL  CHANGE ORDER #10, ACCT NO. 10129-401-140  - COR-42 CB-10 Lighting inverter and lighting - COR-47 Added plaster work on 1st and ground levels  - COR-47 Added plaster work on 1st and ground levels  - COR-48 Add frost walls in MLK entry  - COR-48 Add frost walls in MLK entry  - COR-49 Unforeseen subgrade items  - LUMP SUM  \$19,290.19  - COR-49 Unforeseen subgrade items  - LUMP SUM  \$19,313.42  CHANGE ORDER #11, ACCT NO. 10129-401-140  - Tuckpointing  - COR-52 Added wall framing  - COR-53 Wiring and controls for relocated duct detectors per CB-9  - COR-58 Change marble  - COR-58 Change marble  - LUMP SUM  \$31,33.83  - COR-58 Change marble  - LUMP SUM  \$10,000  - \$13,000  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,00  - \$10,0		- COR-40 Added door security and data	1.00	LUMP SUM	\$19,999.87		\$19,999.87	0.10	\$2,000.01	0.75	\$15,000.00	0.85	\$17,000.00	85.0%
- COR-42 CB-10 Lighting inverter and lighting lighting lighting lighting lighting lighting and ground levels  - COR-47 Added plaster work on 1st and ground levels  - COR-47 Added plaster work on 1st and ground levels  - COR-48 Add frost walls in MLK entry  1.00			1.00	LUMP SUM	\$157,655.00			0.00		1.00				100.0%
Highting	CHANG	E ORDER #10, ACC'T NO. 10129-401-140												
and ground levels 1.00 LUMP SUM \$71,995.74 \$71,995.74 1.00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$1,00 \$		lighting	1.00	LUMP SUM	\$14,013.50		\$14,013.50	0.00	\$0.00	1.00	\$14,013.50	1.00	\$14,013.50	100.0%
- COR-49 Unforeseen subgrade items 1.00 LUMP SUM \$1,889.76 \$1,889.76 0.00 \$0.00 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,889.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1.00 \$1,899.76 1			1.00	LUMP SUM	\$71,996.74		\$71,996.74	0.00	\$0.00	1.00	\$71,996.74	1.00	\$71,996.74	100.0%
- COR 50 CB-8 Casework on 1st floor, MEP changes to accomodate FFE		- COR-48 Add frost walls in MLK entry	1.00	LUMP SUM	\$19,290.19		\$19,290.19	0.00	\$0.00	1.00	\$19,290.19	1.00	\$19,290.19	100.0%
MEP changes to accomodate FFE CHANGE ORDER #10 TOTAL  CHANGE ORDER #11, ACC'T NO. 10129-401-140 - Tuckpointing 1.00 LUMP SUM \$219,231.96  CHANGE ORDER #12, ACC'T NO. 10129-401-140 - COR-52 Added wall framing 1.00 LUMP SUM \$35,638.30 COR-53 Wiring and controls for relocated duct detectors per CB-9 - COR-54 Continued plaster work on 1st floor and ground levels - COR-55 Unforeseen conditions on ground floor, repair fractured exterior glass, electrical/data changes to accomodate FFE layout - COR-56 Existing door hardware credit 1.00 LUMP SUM \$84,403.88 - COR-58 Change marble 1.00 LUMP SUM \$84,403.88 - COR-58 Change marble 1.00 LUMP SUM \$84,33.88 - COR-58 Change marble 1.00 LUMP SUM \$13,133.08 - \$13,133.08 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$10,00 - \$		- COR-49 Unforeseen subgrade items	1.00	LUMP SUM	\$1,889.76		\$1,889.76	0.00	\$0.00	1.00	\$1,889.76	1.00	\$1,889.76	100.0%
CHANGE ORDER #11, ACCT NO. 10129-401-140 - Tuckpointing 1.00 LUMP SUM \$219,231.96 \$219,231.96 0.46 \$100,000.00 0.21 \$45,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.0		· · · · · · · · · · · · · · · · · · ·	1.00	LUMP SUM	\$19,313.42		\$19,313.42	0.00	\$0.00	1.00	\$19,313.42	1.00	\$19,313.42	100.0%
- Tuckpointing 1.00 LUMP SUM \$219,231.96 \$219,231.96 0.46 \$100,000.00 0.21 \$45,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66 \$145,000.00 0.66		CHANGE ORDER #10 TOTAL					\$126,503.61	·	\$0.00	-	\$126,503.61	-	\$126,503.61	_
CHANGE ORDER #12, ACC'T NO. 10129-401-140  - COR-52 Added wall framing 1.00 LUMP SUM \$35,638.30 \$35,638.30 0.00 \$0.00 1.00 \$35,638.30 1.00 \$35,638.30 0.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 1.00 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.76 \$58,727.70 \$58,727.70 \$58,727.70 \$58,727.70 \$58,727.70 \$58,727.70 \$5	CHANG	E ORDER #11, ACC'T NO. 10129-401-140												
- COR-52 Added wall framing 1.00 LUMP SUM \$35,638.30 \$35,638.30 0.00 \$0.00 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.00 \$35,638.30 1.0		- Tuckpointing	1.00	LUMP SUM	\$219,231.96		\$219,231.96	0.46	\$100,000.00	0.21	\$45,000.00	0.66	\$145,000.00	66.1%
- COR-53 Wiring and controls for relocated duct detectors per CB-9 - COR-54 Continued plaster work on 1st floor and ground levels - COR-55 Unforeseen conditions on ground floor, repair fractured exterior glass, electrical/data changes to accomodate FFE layout - COR-56 Existing door hardware credit - COR-58 Change marble - COR-58 Change marble - COR-58 Change marble - COR-58 Wiring and controls for plants and state of the State of	CHANG	E ORDER #12, ACC'T NO. 10129-401-140												
relocated duct detectors per CB-9  - COR-54 Continued plaster work on 1st floor and ground levels  - COR-55 Unforeseen conditions on ground floor, repair fractured exterior glass, electrical/data changes to accomodate FFE layout  - COR-56 Existing door hardware credit  - COR-58 Change marble  1.00  LUMP SUM  \$30,146.73  \$30,146.73  \$30,146.73  \$30,146.73  0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$0.00  \$1.00  \$30,146.73  1.00  \$30,146.73  1.00  \$44,403.88  \$84,403.88  0.00  \$0.00  \$0.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00  \$1.00			1.00	LUMP SUM	\$35,638.30		\$35,638.30	0.00	\$0.00	1.00	\$35,638.30	1.00	\$35,638.30	100.0%
floor and ground levels  - COR-55 Unforeseen conditions on ground floor, repair fractured exterior glass, electrical/data changes to accomodate FFE layout  - COR-56 Existing door hardware credit  - COR-58 Change marble  1.00  LUMP SUM  \$30,146.73  \$30,146.73  \$30,146.73  \$30,146.73  \$0.00  \$0.00  \$0.00  \$0.00  \$1.00  \$84,403.88  \$84,403.88  \$0.00  \$0.00  \$0.00  \$1.00  \$10,133.08  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$100  \$		•	1.00	LUMP SUM	\$58,727.76		\$58,727.76	0.00	\$0.00	1.00	\$58,727.76	1.00	\$58,727.76	100.0%
ground floor, repair fractured exterior glass, electrical/data changes to accommodate FFE layout  - COR-56 Existing door hardware credit 1.00 LUMP SUM \$15,839.38 \$15,839.38 \$15,839.38 \$10.00 \$0.00 \$0.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$15,839.38 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.00 \$1.		floor and ground levels	1.00	LUMP SUM	\$30,146.73		\$30,146.73	0.00	\$0.00	1.00	\$30,146.73	1.00	\$30,146.73	100.0%
- COR-58 Change marble 1.00 LUMP SUM \$15,839.38 \$15,839.38 0.00 \$0.00 1.00 \$15,839.38 1.00 \$15,839.38		ground floor, repair fractured exterior glass, electrical/data changes to	1.00	LUMP SUM	\$84,403.88		\$84,403.88	0.00	\$0.00	1.00	\$84,403.88	1.00	\$84,403.88	100.0%
		- COR-56 Existing door hardware credit	1.00	LUMP SUM	-\$13,133.08		(\$13,133.08)	0.00	\$0.00	1.00	(\$13,133.08)	1.00	(\$13,133.08)	100.0%
			1.00	LUMP SUM	\$15,839.38		\$15,839.38	0.00	\$0.00	1.00	\$15,839.38	1.00	\$15,839.38	100.0%
- COR-60 Asbestos caulk and glazing removal at additional exterior glass 1.00 LUMP SUM \$11,554.60 \$11,554.60 0.00 \$0.00 \$1.00 \$11,554.60 1.00 \$11,554.60 replacements			1.00	LUMP SUM	\$11,554.60		\$11,554.60	0.00	\$0.00	1.00	\$11,554.60	1.00	\$11,554.60	100.0%
CHANGE ORDER #12 TOTAL \$223,177.57 \$0.00 \$223,177.57 \$223,177.57		•					\$223,177.57	-	\$0.00	<b>.</b>	\$223,177.57		\$223,177.57	_

J. P. CULLEN & SONS, INC. MADISON MUNICIPAL BUILDING RENOVATION CONTRACT NO. 7939 PAYMENT NO. 13

PAYMENT NO		1	2	3	4	5	6	7	8	9	******* #10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
CHANGE OR	DER #13, ACC'T NO. 10129-401-140												
- CC	OR-59 Changes to 3rd floor finishes	1.00	LUMP SUM	\$8,715.90		\$8,715.90	1.00	\$8,715.90	0.00	\$0.00	1.00	\$8,715.90	100.0%
	DR-61 CB-12 Stair detail, ADA wall, hting	1.00	LUMP SUM	\$19,321.55		\$19,321.55	1.00	\$19,321.55	0.00	\$0.00	1.00	\$19,321.55	100.0%
	DR-62 Credit duct cleaning	1.00	LUMP SUM	-\$30,000.00		(\$30,000.00)		(\$30,000.00)		\$0.00		(\$30,000.00)	
	DR-63 CB-13 and other misc cost	1.00	LUMP SUM	\$52,060.75		\$52,060.75	1.00	\$52,060.75	0.00	\$0.00		\$52,060.75	_
CHA	ANGE ORDER #13 TOTAL					\$50,098.20		\$50,098.20		\$0.00		\$50,098.20	
CHANGE OR	DER #14, ACC'T NO. 10129-401-140												
- CE wor	3-14 and miscellaneous additional k	1.00	LUMP SUM	\$125,461.75		\$125,461.75	0.00	\$0.00	0.00	\$0.00	0.00	\$0.00	0.0%
GRAND TOTA	ALS (CONTRACT TOTALS PLUS CHA	NGE ORDERS)			\$21,167,373.87		:	\$677,996.20	= =	\$19,953,683.90	= :	\$20,631,680.10	= 97.47%