APPLICATION AND CERTIFICATE FOR PAYMENT CITY OF MADISON ENGINEERING DIVISION

Project: POLICE DEPARTMENT MIDTOWN DISTRICT	•
FIGURE COMPRESSION CONTRACTOR CON	
Contract Number: 7726	Payment Number: 15
DO NOT WRITE IN THIS BOX - TO BE COMPLETED BY C	ITY ENGINEERING PERSONNEL ONLY
TOTAL FROM PAGE: 4	7,763,473.59
LESS RETAINAGE:	194,627.39
SUBTOTAL:	7,568,846.20
LESS PREVIOUS PAYMENTS:	7,511,618.65
CURRENT PAYMENT DUE:	\$ 57,227.55
and that the current payment is now due. Avid Compa. CONTRACTOR: MIRON CONSTRUCTION CO., INC. INSPECTOR'S CERTIFICATE FOR PAYMENT:	•
The undersigned inspector certifies that to the best of he by this application for payment has been completed in and that the contractor is entitled to payment for the an	accordance with the contract documents,
INSPECTOR INSPECTOR	11/30/18 DATE
PLEASE PROVIDE THE TIME PERIOD FOR THIS PAYMENT REQUEST	TO: 11.30.2018
4	ORKED ON PROJECT DURING THIS PERIOD:
PLEASE PROVIDE THE CONTRACTOR/SUBCONTRACTORS THAT WO	
Miron Cat	tell
Miron Cat	

PARTIAL PAYMENTS CAN BE PROCESSED EVERY TWO WEEKS.

RETAINAGE IS ONLY 5% OF TOTAL WORK COMPLETED UNTIL 50% OF THE WORK IS DONE AND THEN RETAINAGE IS 2.5% OF THE TOTAL CONTRACT DOLLARS (COLUMN #4)!!!! ACCOUNT NO. 10390-31-140

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

MIRON CONSTRUCTION CO., INC.
POLICE DEPARTMENT MIDTOWN DISTRICT
CONTRACT NO. 7726
PAYMENT NO. 15

	ACT NO. 7726 NT NO. 15					İ	1		1		******		
		1	2	3	4	5	6	7	8	9	#10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
ACCOU	NT NO. 10390-31-140												
90001	Base Bid	1.00	Lump Sum	\$7,518,738.00	\$7,518,738.00		0.01	\$52,031.54	0.99	\$7,435,219.58	1.00	\$7,487,251.12	99.6%
CONTR	ACT TOTALS				\$7,518,738.00	•	•	\$52,031.54	-	\$7,435,219.58	•	\$7,487,251.12	99.58%
CHANG	E ORDER #1, ACC'T NO. 10390-31-140												
	- COR-1 EXTRA DEMO	1.00	Lump Sum	\$5,991.23		\$5,991.23	0.00	\$0.00	1.00	\$5,991.23	1.00	\$5,991.23	100.0%
	- COR-2 UPGRADED BALL VALVES	1.00	Lump Sum	\$1,800.33		\$1,800.33	0.00	\$0.00		\$1,800.33	1.00	\$1,800.33	100.0%
	- COR-5 DELETE IRRIGATION	1.00	Lump Sum	-\$22,266.46		(\$22,266.46)	0.00	\$0.00	1.00	(\$22,266.46)		(\$22,266.46)	' I
	- COR-6 REMOVE WESTMORLAND - COR-7 DOOR CHANGES	1.00	Lump Sum Lump Sum	-\$3,662.26 \$1,402.79		(\$3,662.26) \$1,402.79	0.00 0.00	\$0.00	1.00 1.00	(\$3,662.26) \$1,402.79	1.00 1.00	(\$3,662.26) \$1,402.79	100.0% 100.0%
	- COR-8 STRUCTURAL AND PATIO CHANGES	1.00 1.00	Lump Sum	\$8,704.91		\$8,704.91	0.00	\$0.00 \$0.00		\$8,704.91	1.00	\$8,704.91	100.0%
	- COR-9 UNDERCUTTING FOR FOOTING	1.00	Lump Sum	\$2,793.94		\$2,793.94	0.00	\$0.00	1.00	\$2,793.94	1.00	\$2,793.94	100.0%
	- COR-10 A/E REVISIONS	1.00	Lump Sum	\$3,823.54		\$3,823.54	0.00	\$0.00		\$3,823.54	1.00	\$3,823.54	100.0%
	- COR-11 COUNTERTOP ADJUSTMENTS	1.00	Lump Sum	\$1,039.54		\$1,039.54	0.00	\$0.00	1.00	\$1,039.54	1.00	\$1,039.54	100.0%
	CHANGE ORDER #1 TOTAL					(\$372.44)		\$0.00		(\$372.44))	(\$372.44))
CHANG	E ORDER #2, ACC'T NO. 10390-31-140												
	- COR-12 Changes to the 54" Storm Sewer on Midtown PD Site - COR-13 Changes to ADA operator,	1.00	Lump Sum	-\$1,988.81		(\$1,988.81)	0.00	\$0.00	1.00	(\$1,988.81)	1.00	(\$1,988.81)	100.0%
	louver opening, landscaping at flag pole, addition of a gate in the fence and some structural steel additions	1.00	Lump Sum	\$8,046.97		\$8,046.97	0.00	\$0.00	1.00	\$8,046.97	1.00	\$8,046.97	100.0%
	- COR-14 Changes to flushable floor drains in holding area (QTY 2) and changes to shower enclosures	1.00	Lump Sum	\$2,648.45		\$2,648.45	0.00	\$0.00	1.00	\$2,648.45	1.00	\$2,648.45	100.0%
	- COR-15 Addition of coverboard under roof section that will have PV panels	1.00	Lump Sum	\$10,453.50		\$10,453.50	0.00	\$0.00	1.00	\$10,453.50	1.00	\$10,453.50	100.0%
	CHANGE ORDER #2 TOTAL					\$19,160.11		\$0.00	_	\$19,160.11	.	\$19,160.11	_
CHANG	E ORDER #3, ACC'T NO. 10390-31-140												
	- COR-16 Undercutting - COR-17 Removal of Old Foundation -	1.00	Lump Sum	\$1,021.06		\$1,021.06	0.00	\$0.00	1.00	\$1,021.06	1.00	\$1,021.06	100.0%
	unforseen	1.00	Lump Sum	\$6,168.62		\$6,168.62	0.00	\$0.00		\$6,168.62		\$6,168.62	100.0%
	- COR-18 Changes to Capstone Style CHANGE ORDER #3 TOTAL	1.00	Lump Sum	\$3,391.58		\$3,391.58 \$10,581.26	0.00	\$0.00 \$0.00	1.00	\$3,391.58 \$10,581.26	1.00	\$3,391.58 \$10,581.26	-
OUANO.	E ODDED #4 400F NO 40000 04 440									,			
CHANG	E ORDER #4, ACC'T NO. 10390-31-140					İ	1		i		ĺ		ĺ
	- COR-19 Electrical and Tech changes to Incident, Briefing and Community	1.00	Lump Sum	\$21,409.72		\$21,409.72	0.00	\$0.00	1.00	\$21,409.72	1.00	\$21,409.72	100.0%
	Rooms - COR-20 Extra Windshield Tags for	1.00	Lump Sum	\$1,163.61		\$1,163.61	0.00	\$0.00	1.00	\$1,163.61	1.00	\$1,163.61	100.0%
	squads to open garage doors		•			•		•		. ,		. ,	
	- COR-21 Safety Railing for Roof Hatch	1.00	Lump Sum	\$1,672.56		\$1,672.56	0.00	\$0.00	1.00	\$1,672.56	1.00	\$1,672.56	100.0%

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

MIRON CONSTRUCTION CO., INC.
POLICE DEPARTMENT MIDTOWN DISTRICT
CONTRACT NO. 7726
PAYMENT NO. 15

FATIVICI	NT NO. 13	1	2	3	4	5	6	7	8	9	#10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
	- COR-22 Modifications to Window Head/Jamb Detail	1.00	Lump Sum	\$905.73		\$905.73	0.00	\$0.00	1.00	\$905.73	1.00	\$905.73	100.0%
	- COR-23 Revised sink at Breakroom 116	1.00	Lump Sum	\$191.11		\$191.11	0.00	\$0.00	1.00	\$191.11	1.00	\$191.11	100.0%
	- COR-24 CB#8/ASI-6 Floor finish changes and other minor changes	1.00	Lump Sum	\$11,758.60		\$11,758.60	0.00	\$0.00	1.00	\$11,758.60	1.00	\$11,758.60	100.0%
	CHANGE ORDER #4 TOTAL					\$37,101.33		\$0.00		\$37,101.33		\$37,101.33	
CHANG	E ORDER #5, ACC'T NO. 10390-31-140												
	- COR-25 Retaining Wall and Plywood	1.00	Lump Sum	\$22,356.63		\$22,356.63	0.00	\$0.00	1.00	\$22,356.63	1.00	\$22,356.63	100.0%
	- COR-26 Audio Video Equipment and Install	1.00	Lump Sum	\$65,826.12		\$65,826.12	0.00	\$0.00	1.00	\$65,826.12	1.00	\$65,826.12	100.0%
	- COR-27 Driveway and Parking Lot Undercutting	1.00	Lump Sum	\$8,550.14		\$8,550.14	0.00	\$0.00	1.00	\$8,550.14	1.00	\$8,550.14	100.0%
	- COR-28 Cutting and Patching of Floor for A/V Changes	1.00	Lump Sum	\$1,661.10		\$1,661.10	0.00	\$0.00	1.00	\$1,661.10	1.00	\$1,661.10	100.0%
	- COR-29 Base Mount Exterior Light Fixtures instead of Direct Bury	1.00	Lump Sum	\$2,138.22		\$2,138.22	0.02	\$38.49	0.98	\$2,099.73	1.00	\$2,138.22	100.0%
	CHANGE ORDER #5 TOTAL					\$100,532.21	-	\$38.49	-	\$100,493.72	•	\$100,532.21	100.00%
CHANG	E ORDER #6, ACC'T NO. 10390-31-140												
CHANG	- COR-30 Storm Pipe Reconfiguration	1.00	Lump Sum	\$8,138.95		\$8,138.95	0.00	\$0.00	1.00	\$8,138.95	1.00	\$8,138.95	100.0%
	- COR-31 Added Labor by IBS to install 24 WAP's	1.00	Lump Sum	\$1,130.88		\$1,130.88	0.00	\$0.00	1.00	\$1,130.88	1.00	\$1,130.88	100.0%
	CHANGE ORDER #6 TOTAL					\$9,269.83	-	\$0.00	J _	\$9,269.83	J .	\$9,269.83	J
CHANG	E ORDER #7, ACC'T NO. 10390-31-140												
	- COR-32 Addition of Ladder in elevator shaft above cab to allow access to duct smoke detector at top of shaft	1.00	Lump Sum	\$1,089.86		\$1,089.86	0.00	\$0.00	1.00	\$1,089.86	1.00	\$1,089.86	100.0%
	- COR-33 Changed door hardware on door B001-1 to a delayed access hardware based on Fire Department review	1.00	Lump Sum	\$1,886.93		\$1,886.93	0.00	\$0.00	1.00	\$1,886.93	1.00	\$1,886.93	100.0%
	- COR-34 Time and Material work related to rerouting some piping and additional shrouds to avoid structural elements	1.00	Lump Sum	\$3,437.18		\$3,437.18	0.00	\$0.00	1.00	\$3,437.18	1.00	\$3,437.18	100.0%
	CHANGE ORDER #7 TOTAL					\$6,413.97	-	\$0.00	- -	\$6,413.97		\$6,413.97	1
CHANG	E ORDER #8, ACC'T NO. 10390-31-140												
	- COR-35 Shower compartments	1.00	Lump Sum	\$1,503.12		\$1,503.12	0.00	\$0.00	1.00	\$1,503.12	1.00	\$1,503.12	100.0%
	- COR-36 Two new breakroom cabinets	1.00	Lump Sum	\$1,571.86		\$1,571.86	0.00	\$0.00	1.00	\$1,571.86	1.00	\$1,571.86	100.0%
	- COR-37 Display mounts in Room 108	1.00	Lump Sum	\$388.57		\$388.57	0.22	\$84.32	0.78	\$304.25	1.00	\$388.57	100.0%
	- COR-39 Addition of concrete motorcycle parking area	1.00	Lump Sum	\$1,724.93		\$1,724.93	0.00	\$0.00	1.00	\$1,724.93	1.00	\$1,724.93	100.0%
	CHANGE ORDER #8 TOTAL					\$5,188.48	·	\$84.32	- -	\$5,104.16	-	\$5,188.48	100.00%
CHANG	E ORDER #9, ACC'T NO. 10390-31-140												
	- COR-38 Parking lot undercutting	1.00	Lump Sum	\$34,959.04		\$34,959.04	0.00	\$0.00	1.00	\$34,959.04	1.00	\$34,959.04	100.0%

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

MIRON CONSTRUCTION CO., INC.
POLICE DEPARTMENT MIDTOWN DISTRICT
CONTRACT NO. 7726
PAYMENT NO. 15

I ATMILI	IT NO. 15	1	2	3	4	5	6	7	8	9	******* #10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETI
	- COR-40 Replacement flat manhole cover	1.00	Lump Sum	\$184.78		\$184.78	0.00	\$0.00	1.00	\$184.78	1.00	\$184.78	100.0%
	- COR-41 Moisture mitigation	1.00	Lump Sum	\$23,060.00		\$23,060.00	0.22	\$5,073.20	0.78	\$17,986.80	1.00	\$23,060.00	100.0%
	- COR-42 Solar panel support	1.00	Lump Sum	\$3,432.23		\$3,432.23	0.00	\$0.00	1.00	\$3,432.23	1.00	\$3,432.23	100.0%
	modification - COR-43 Fencing modifications	1.00	Lump Sum	\$6,805.33		\$6,805.33	0.00	\$0.00	1.00	\$6,805.33	1.00	\$6,805.33	
	CHANGE ORDER #9 TOTAL	1.00	Lump Jum	φ0,003.33		\$68,441.38	0.00	\$5,073.20	1.00	\$63,368.18	1.00	\$68,441.38	_
CHANGE	E ORDER #10, ACC'T NO. 10390-31-140												
	- COR-44 Modify the break room casework to accomodate the donated Sub Zero refrigerators	1.00	Lump Sum	\$3,976.09		\$3,976.09	0.00	\$0.00	1.00	\$3,976.09	1.00	\$3,976.09	100.0%
	- COR-45 Add a data jack for a multifunction copier	1.00	Lump Sum	\$294.60		\$294.60	0.00	\$0.00	1.00	\$294.60	1.00	\$294.60	100.0%
	- COR-46 Undo COR-36 that is unneeded for ladder access in the elevator shaft	1.00	Lump Sum	-\$1,089.86		(\$1,089.86)	0.00	\$0.00	1.00	(\$1,089.86)	1.00	(\$1,089.86)	100.0%
	- COR-47 Add shower seats to the bathroom	1.00	Lump Sum	\$1,015.34		\$1,015.34	0.00	\$0.00	1.00	\$1,015.34	1.00	\$1,015.34	100.0%
	- COR-48 Remove old foundation at the bio-retention basin location	1.00	Lump Sum	\$4,237.47		\$4,237.47	0.00	\$0.00	1.00	\$4,237.47	1.00	\$4,237.47	100.0%
	- COR-49 Add signs to bathroom and elevator equipment room	1.00	Lump Sum	\$152.23		\$152.23	0.00	\$0.00	1.00	\$152.23	1.00	\$152.23	100.0%
	- COR-50 Modify a sink to be ADA accessible	1.00	Lump Sum	\$152.93		\$152.93	0.00	\$0.00	1.00	\$152.93	1.00	\$152.93	100.0%
	- COR-51 Add data outlets in rooms 137 and 138 for interview cameras	1.00	Lump Sum	\$1,085.47		\$1,085.47	0.00	\$0.00	1.00	\$1,085.47	1.00	\$1,085.47	100.0%
	- COR-52 Add additional corner guards requested by MPD after move in. Guards to be installed by MPD Staff.	1.00	Lump Sum	\$217.04		\$217.04	0.00	\$0.00	1.00	\$217.04	1.00	\$217.04	100.0%
	CHANGE ORDER #10 TOTAL					\$10,041.31		\$0.00		\$10,041.31		\$10,041.31	1
CHANGE	E ORDER #11, ACC'T NO. 10390-31-140												
	- COR-53 Radiator shrouds	1.00	Lump Sum	\$1,348.79		\$1,348.79	0.00	\$0.00	1.00	\$1,348.79	1.00	\$1,348.79	100.0%
	- COR-54 Elevator work due to Bi	1.00	Lump Sum	\$6,612.60		\$6,612.60	0.00	\$0.00	1.00	\$6,612.60	1.00	\$6,612.60	100.0%
	- COR-55 Credit for fence staining	1.00	Lump Sum	-\$1,519.68		(\$1,519.68)	0.00	\$0.00	1.00	(\$1,519.68)		(\$1,519.68)	
	- COR-56 Electrical work (power)	1.00	Lump Sum	\$512.68		\$512.68	0.00	\$0.00	1.00	\$512.68	1.00	\$512.68	100.0%
	- COR-57 Electrical work (switches) - COR-58 HDMI connection Briefing	1.00 1.00	Lump Sum Lump Sum	\$1,335.40 \$1,575.24		\$1,335.40 \$1,575.24	0.00	\$0.00 \$0.00	1.00	\$1,335.40 \$1,575.24	1.00	\$1,335.40 \$1,575.24	100.0%
	Room	1.00	Lump Sum	φ1,3/3.24		Φ1,373.24	0.00	φυ.υυ	1.00	φ1,5 <i>1</i> 3.24	1.00	φ1,3/3.24	100.09
	CHANGE ORDER #11 TOTAL					\$9,865.03		\$0.00		\$9,865.03		\$9,865.03	
GRAND	TOTALS (CONTRACT TOTALS PLUS CHAN	IGE ORDERS)			\$7,794,960.47		•	\$57,227.55	<u>. </u>	\$7,706,246.04	•	\$7,763,473.59	- 99.60%