

2018 PARKING GARAGE MAINTENANCE

CONTRACT NO. 8190

DATE: 5/3/18

ProAxis LLC

| Item | Quantity | Price | Extension |
|---|----------|-------------|--------------|
| Section B: Proposal Page | | | |
| 1 - Topside of Slab Repair Below One Layer of Reinforcing Steel - SF | 1310.00 | \$35.62 | \$46,662.20 |
| 2 - Topside of Slab Repair Below Two Layers of Reinforcing Steel - SF | 1050.00 | \$38.79 | \$40,729.50 |
| 3 - Concrete Repair at Vertical Surfaces of Columns/Walls/Beams - SF | 75.00 | \$113.38 | \$8,503.50 |
| 4 - Concrete Repair Overhead at Slabs and Beams - SF | 200.00 | \$130.45 | \$26,090.00 |
| 5 - Concrete Repair at Top of Columns - SF | 45.00 | \$140.31 | \$6,313.95 |
| 6 - Concrete Repair at Joist Stems - LF | 40.00 | \$173.89 | \$6,955.60 |
| 7 - Thicken Column Sections - EA | 2.00 | \$3,398.33 | \$6,796.66 |
| 8 - Repair Cracked Stair Treads - SF | 15.00 | \$170.97 | \$2,564.55 |
| 9 - Column Base Repair - EA | 28.00 | \$341.99 | \$9,575.72 |
| 10 - Epoxy Inject Concrete Cracks - LF | 30.00 | \$73.84 | \$2,215.20 |
| 11 - Rout and Seal Cracks - LF | 140.00 | \$6.62 | \$926.80 |
| 12 - Replace Sealant at Horizontal & Vertical Surfaces - LF | 290.00 | \$11.69 | \$3,390.10 |
| 13 - Full System Membrane Placement - SF | 9200.00 | \$5.79 | \$53,268.00 |
| 14 - Membrane Wear Coat & Top Coat Placement - SF | 26000.00 | \$2.77 | \$72,020.00 |
| 15 - Expansion Joint Header Material Replacement - LF | 235.00 | \$22.56 | \$5,301.60 |
| 16 - Replace Expansion Joint - Wing Joint - LF | 170.00 | \$102.16 | \$17,367.20 |
| 17 - Replace Expansion Joint - 4" Wide Polyurethane Seal - LF | 25.00 | \$134.51 | \$3,362.75 |
| 18 - Replace Expansion Joint - 8" Wide Polyurethane Seal - LF | 60.00 | \$120.85 | \$7,251.00 |
| 19 - Calcium Silicate Sealer - SF | 7500.00 | \$0.01 | \$75.00 |
| 20 - Guardrail Anchor Plates - EA | 81.00 | \$104.40 | \$8,456.40 |
| 21 - Repaint All Blue Guardrails and Bumper Stops - LS | 1.00 | \$19,069.43 | \$19,069.43 |
| 22 - Grit-Blast and Repaint Support Angles at Knock Out Slab - LF | 240.00 | \$29.83 | \$7,159.20 |
| 23 - Repaint Original Tapered Columns - EA | 54.00 | \$82.83 | \$4,472.82 |
| 24 - Clean and Repaint Steel Doors and Frames - EA | 8.00 | \$268.41 | \$2,147.28 |
| 25 - Replace Finishing at Framed Beam at OC - LS | 1.00 | \$2,147.30 | \$2,147.30 |
| 25 Items | Totals | | \$362,821.76 |