APPLICATION AND CERTIFICATE FOR PAYMENT CITY OF MADISON ENGINEERING DIVISION

Project Manager:	JON EVANS		Page 1 of_	4			
Project: METRO 1	TRANSIT PHASE 3A - MAINTENAN	CE AND DRIVER FACILIT	Y IMPROVEMENTS				
Contract Number:	8981		Payment Number:	10			
DO NOT WRITE	IN THIS BOX - TO BE COMP	PLETED BY CITY ENGINEE	RING PERSONNEL ONL	_Y			
TOTAL FROM PAGE:	3		7,646,258.38				
LESS RETAINAGE:			246,023.44				
SUBTOTAL:			7,400,234.94				
LESS PREVIOUS PAY	YMENTS:		6,921,028.67				
CURRENT PAYMENT	DUE:		479,206.27				
and that COMIRE INSPECTOR'S CERTIFIED THE UNder	the current payment has been continued the current payment is now due. CTOR: J. P. CVLLEN & SONS IFICATE FOR PAYMENT: Description for payment has been so a polication for payment has been continued in the current payment between the current payment has been continued in the current payment payment between the current payment	بر المحرر , INC. the best of his/her knowle	DATE edge, the work covered	2022 a			
and that	pplication for payment has been co the contractor is entitled to paymen	•	i.				
Mike INSPEC	S chuchardt TOR		7/11/22 DATE	2			
	TIME PERIOD FOR THIS PAYMEN		FROM: Last 6/1/22 TO: Billed 6/30/	/22			
PLEASE PROVIDE THE HJ Pertzborn	CONTRACTOR/SUBCONTRACTOR KVA Electric	Southport	OJECT DURING THIS I	<u>'ERIOD:</u>			
JP Cullen	Maly Roofing	Statz & Harrop					
KMS Excavating	Monona Plumbing	Zander					

NOTE: SIGNED PAYMENT REQUEST SHALL BE SUBMITTED TO THE ENGINEER/INSPECTOR.

PARTIAL PAYMENTS CAN BE PROCESSED EVERY TWO WEEKS.

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

J. P. CULLEN & SONS, INC.
METRO TRANSIT PHASE 3A - MAINTENANCE AND DRIVER FACILITY IMPROVEMENTS
CONTRACT NO. 8981

PAYME	NT NO. 10	1	2	3	4	5	6	7	8	9	******* #10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
ACCOU	NT NO. 11230-85-140-114403												
90000	BASE BID	1.00	Lump Sum	\$8,653,930.00	\$8,653,930.00		0.04	\$364,198.30	0.73	\$6,293,534.25	0.77	\$6,657,732.55	76.93%
ALTER	NATE NO. 1:												
90001	ALTERNATE NO. 1. SEE SPECIFICATION 012300 - ALTERNATES AND DRAWINGS AD101F AND A-101F. ALL WORK ASSOCIATED WITH AREA F, FIRST FLOOR ONLY, AS IDENTIFIED PER DRAWING G131. THIS GENERALLY INCLUDES ROOMS 1301, 1302, 1303, 1304, 1305, 1306, 1308, 1309, 1311, ALONG WITH ALL ASSOCIATED STRUCTURAL, EQUIPMENT, FIRE PROTECTION, PLUMBING, HVAC, ELECTRICAL AND COMMUNICATIONS SYSTEMS.	1.00	Lump Sum	\$759,017.00	\$759,017.00		0.10	\$75,901.70	0.75	\$569,262.75	0.85	\$645,164.45	85.00%
CONTR	ACT TOTALS				\$9,412,947.00	•		\$440,100.00		\$6,862,797.00		\$7,302,897.00	- 77.58%
CHANG	E ORDER #1, ACC'T NO. 11230-85-140-11440	03				•	•		1	ı	,		1
	- COR-1 Remove abandoned steam pipe	1.00	Lump Sum	\$15,374.89		\$15,374.89	0.00	\$0.00	1.00	\$15,374.89	1.00	\$15,374.89	100.00%
	- Cor-2 Patch asphalt	1.00	Lump Sum	\$2,059.29		\$2,059.29	0.00	\$0.00	1.00	\$2,059.29	1.00	\$2,059.29	100.00%
	- COR-3 Reroute water lateral due to unforseen duct bank	1.00	Lump Sum	\$2,526.52		\$2,526.52	0.00	\$0.00	1.00	\$2,526.52	1.00	\$2,526.52	100.00%
	- COR-4 Credit for change in holding tank	1.00	Lump Sum	-\$3,210.97		(\$3,210.97)	0.00	\$0.00	1.00	(\$3,210.97)	1.00	(\$3,210.97)	100.00%
	- COR-5 Plumbing permit reimbursement	1.00	Lump Sum	\$2,576.21		\$2,576.21	0.00	\$0.00	1.00	\$2,576.21	1.00	\$2,576.21	100.00%
	CHANGE ORDER #1 TOTAL					\$19,325.94		\$0.00		\$19,325.94		\$19,325.94	1
CHANG	E ORDER #2, ACC'T NO. 11230-85-140-11440	03											
	- COR-6 Underground storm pipe reroute for bus pit	1.00	Lump Sum	\$3,986.71		\$3,986.71	0.00	\$0.00	1.00	\$3,986.71	1.00	\$3,986.71	100.00%
	- COR-14 CB-01 Mechanical changes and commissioning adder	1.00	Lump Sum	\$9,584.12		\$9,584.12	0.00	\$0.00	0.00	\$0.00	0.00	\$0.00	0.00%
	- COR-15 Removal and disposal of contaminated soils found at new bus lifts	1.00	Lump Sum	\$37,857.04		\$37,857.04	0.00	\$0.00	1.00	\$37,857.04	1.00	\$37,857.04	100.00%
	CHANGE ORDER #2 TOTAL					\$51,427.87	<u>!</u>	\$0.00	<u>.</u>	\$41,843.75	I	\$41,843.75	<u> </u>

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

J. P. CULLEN & SONS, INC.
METRO TRANSIT PHASE 3A - MAINTENANCE AND DRIVER FACILITY IMPROVEMENTS
CONTRACT NO. 8981

TITIM TYPE OF WORK SETIMATED UNITS WIND WIND COLLARS DOLLARS	PAYMEN	T NO. 10						1				*****		
TIME OF WORK QUANTIES UNITS BID DOLLARS DOLLARS APPL EXTENSION DILIES EXTENSION UNITS EXTENSION COMPLETE COLLARS COLLARS APPL STANSON COMPLETE COLLARS			1	2	3	4	5	6	7	8	9	#10	11	12
-COR-16 CB-02 Door hardware and glazing review (COR-16 CB-02 Door hardware and glazing review (COR-16 CB-04 Change fueling Lange view) -COR-16 CB-04 Change fueling Lange William (COR-16 CB-04 Change) -COR-16 CB-04 Change fueling Lange William (COR-16 CB-04 Change) -COR-16 CB-04 Change fueling Lange William (COR-16 CB-04 Change) -COR-16 CB-04 Change fueling Lange William (COR-16 CB-04 CB-	ITEM	TYPE OF WORK		UNITS					EXTENSION		EXTENSION		EXTENSION	
glazing review - COR-12 Go-4 Change flueling - 1.00 - Lump Sum	CHANGE	ORDER #3, ACC'T NO. 11230-85-140-11440)3				1							
equipment 1.00 Lump Sum \$18,546.00 \$10,666.00 0.00 \$0.00 1.00 \$10,666.00 1		glazing review	1.00	Lump Sum	\$2,611.00		\$2,611.00	0.00	\$0.00	1.00	\$2,611.00	1.00	\$2,611.00	100.00%
- COR-31 Sanitary lateral pitch issues 1.00 Lump Sum 510,646.00 (310,646.00 1.00 510,646.00 1.			1.00	Lump Sum	\$18,546.00		\$18,546.00	0.00	\$0.00	1.00	\$18,546.00	1.00	\$18,546.00	100.00%
- COR-21 Change in convector cabinet 1,00		- COR-19 Sanitary lateral pitch issues		•										
For radiant heat		-		Lump Sum	-\$1,400.00		(\$1,400.00)	0.00	\$0.00	1.00	(\$1,400.00)	1.00	(\$1,400.00)	100.00%
stands to each bus lift (9)		for radiant heat	1.00	Lump Sum	\$741.00		\$741.00	0.00	\$0.00	1.00	\$741.00	1.00	\$741.00	100.00%
tanks CHANGE ORDER 81 TOTAL			1.00	Lump Sum	\$19,624.00		\$19,624.00	0.00	\$0.00	1.00	\$19,624.00	1.00	\$19,624.00	100.00%
### COR-26 Mechanical electrical coordination			1.00	Lump Sum	\$1,195.00		\$1,195.00	0.00	\$0.00	0.00	\$0.00	0.00	\$0.00	0.00%
- COR-25 Change lot plumbing drains and mechanics sink		CHANGE ORDER #3 TOTAL					\$51,963.00	•	\$0.00	•	\$50,768.00	•	\$50,768.00	•
coordination 1.00 Lump Sum 88,865.00 \$8,865.00 \$0.00 \$0.00 \$0.00 \$1.00 \$24,748.00 \$100.00% \$8,865.00 \$100.00% \$8,865.00 \$100.00% \$8,865.00 \$100.00% \$8,865.00 \$100.00% \$1,4318.31 \$1.00 Lump Sum \$1,782.00 \$1,782.00 \$1,00 \$1,00 \$1,782.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$10,00% \$10,950.00 \$1.00 \$10,950.00 \$10,00% \$10,950.00 \$10,00% \$10,950.00 \$10,00 \$10,950.00 \$10,00% \$10,950.00 \$10,950	CHANGE	ORDER #4, ACC'T NO. 11230-85-140-11440	03											
vertical storage unit			1.00	Lump Sum	\$8,865.00		\$8,865.00	0.00	\$0.00	1.00	\$8,865.00	1.00	\$8,865.00	100.00%
cancellation 1.00 Lump Sum \$1,43,18.31		<u> </u>	1.00	Lump Sum	\$24,748.00		\$24,748.00	0.00	\$0.00	1.00	\$24,748.00	1.00	\$24,748.00	100.00%
framing and ductwork reroute near part storage storage storage consistency consistency consistency consistency consistency con			1.00	Lump Sum	-\$14,318.31		(\$14,318.31)	0.00	\$0.00	1.00	(\$14,318.31)	1.00	(\$14,318.31)	100.00%
Storage CCR-20 CB-96 Added plumbing drains and mechanics sink 1.00 Lump Sum \$10,950.00 \$10,950.00 \$10,950.00 1.00 \$10,950.00 1.00 \$10,950.00 100.00%														
and mechanics sink -COR-31 CB-07 Change in layout to equipment at Maintenance B mezzanine CHANGE ORDER #4 TOTAL **S3,074.00 **COR-35 CB-08 Door and hardware revisions -COR-36 Mechanical changes to UH-30 -COR-37 Bar joist reinforcements for MEPF hangers -COR-38 Add grout to bearing wall -COR-38 Add grout to bearing wall -COR-39 Add grease distibution system -COR-31 CB-09 Add greased and generator -COR-31 CB-09 Add greased A		storage	1.00	Lump Sum	\$1,782.00		\$1,782.00	0.00	\$0.00	1.00	\$1,782.00	1.00	\$1,782.00	100.00%
equipment at Maintenance B mezzanine CHANGE ORDER #4 TOTAL CHANGE ORDER #5, ACCT NO. 11230-85-140-114403 - COR-35 CB-08 Door and hardware revisions - COR-36 Mechanical changes to UH-30 - COR-37 Bar joist reinforcements for MEPF hangers - COR-38 Add grout to bearing wall - COR-38 Add grout to bearing wall - COR-39 Add grease distibution system 1.00 - Lump Sum \$13,110.00 - COR-39 Add grease distibution system 1.00 - Lump Sum \$9,450.00 - COR-37 Bar joist reinforcements for MEPF hangers - COR-38 Add grout to bearing wall - COR-39 Add grease distibution system 1.00 - COR-39 Add grease distibution system 1.00 - COR-39 CR-30 Special S			1.00	Lump Sum	\$10,950.00		\$10,950.00	0.00	\$0.00	1.00	\$10,950.00	1.00	\$10,950.00	100.00%
CHANGE ORDER #5, ACCT NO. 11230-85-140-114403 - COR-35 CB-08 Door and hardware revisions - COR-36 Mechanical changes to UH-30 - COR-36 Mechanical changes to UH-30 - COR-37 Bar joist reinforcements for MEPF hangers - COR-38 Add grout to bearing wall - COR-38 Add grout to bearing wall - COR-39 Add grease distibution system - COR-39 Add grease distibution system - COR-39 Add greated file detrical gear and generator procurement delay impacts - COR-41 CB-10 Added parts office and wall at wash bay equipment - COR-42 Temporary electrical connections until new electrical - COR-42 Temporary electrical - COR-43 Temporary electrical - COR-45 Temporary electrical - COR-46 Temporary electrical - COR-47 Temporary electrical - COR-48 Temporary electrical - COR-48 Temporary electrical - COR-49 Temporary electrical - COR-40 Temporary electrical - COR-4			1.00	Lump Sum	\$3,074.00		\$3,074.00	0.00	\$0.00	1.00	\$3,074.00	1.00	\$3,074.00	100.00%
- COR-35 CB-08 Door and hardware revisions 1.00		CHANGE ORDER #4 TOTAL					\$35,100.69	ı	\$0.00	1	\$35,100.69		\$35,100.69	1
revisions 1.00	CHANGE	ORDER #5, ACC'T NO. 11230-85-140-11440	03											
- COR-37 Bar joist reinforcements for MEPF hangers 1.00 Lump Sum \$13,110.00 \$13,110.00 \$0.00 \$0.00 \$0.00 \$1.00 \$13,110.00 \$13,110.00 \$100.00% \$0.00 \$0			1.00	Lump Sum	\$12,755.00		\$12,755.00	0.00	\$0.00	1.00	\$12,755.00	1.00	\$12,755.00	100.00%
MEPF hangers 1.00 Lump Sum \$13,110.00 \$13,110.00 \$1.00		- COR-36 Mechanical changes to UH-30	1.00	Lump Sum	\$2,233.00		\$2,233.00	0.00	\$0.00	0.00	\$0.00	0.00	\$0.00	0.00%
- COR-38 Add grout to bearing wall - COR-39 Add grease distibution system - COR-30 Add grease di		•	1.00	Lump Sum	\$13,110.00		\$13,110.00	0.00	\$0.00	1.00	\$13,110.00	1.00	\$13,110.00	100.00%
- Bus lift electrical gear and generator procurement delay impacts 1.00		•	1.00	Lump Sum	\$9,450.00		\$9,450.00	0.00	\$0.00	1.00	\$9,450.00	1.00	\$9,450.00	100.00%
Procurement delay impacts 1.00 Lump Sum \$0.00 \$0		- COR-39 Add grease distibution system	1.00	Lump Sum	\$55,899.00		\$55,899.00	0.00	\$0.00	1.00	\$55,899.00	1.00	\$55,899.00	100.00%
wall at wash bay equipment 1.00 Lump Sum \$84,545.00 \$84,545.00 0.00 \$0.00 \$0.47 \$40,000.00 0.47 \$40,000.00 47.31% - COR-42 Temporary electrical connections until new electrical switchgear arrives 1.00 Lump Sum \$52,072.00 \$52,072.00 0.00 \$0.00 \$0.48 \$25,000.00 0.48 \$25,000.00 48.01%			1.00	Lump Sum	\$0.00		\$0.00	0.00	\$0.00	1.00	\$0.00	1.00	\$0.00	#DIV/0!
connections until new electrical 1.00 Lump Sum \$52,072.00 \$52,072.00 0.00 \$0.00 0.48 \$25,000.00 0.48 \$25,000.00 48.01%		wall at wash bay equipment	1.00	Lump Sum	\$84,545.00		\$84,545.00	0.00	\$0.00	0.47	\$40,000.00	0.47	\$40,000.00	47.31%
		connections until new electrical	1.00	Lump Sum	\$52,072.00		\$52,072.00	0.00	\$0.00	0.48	\$25,000.00	0.48	\$25,000.00	48.01%
							\$230,064.00	I	\$0.00	4	\$156,214.00		\$156,214.00	4

CONTRACTOR/INSPECTOR/ENGINEER SHOULD ONLY COMPLETE COLUMN #10, "TOTAL UNITS"

J. P. CULLEN & SONS, INC.
METRO TRANSIT PHASE 3A - MAINTENANCE AND DRIVER FACILITY IMPROVEMENTS
CONTRACT NO. 8981
PAYMENT NO. 10

PAYMENT NO. 1		1	1 2	3	4	5	6	7	8	9	******* #10	11	12
ITEM	TYPE OF WORK	ESTIMATED QUANTITIES	UNITS	UNIT PRICE BID	CONTRACT DOLLARS	C. O. DOLLARS	UNITS THIS APPL.	EXTENSION	UNITS PREV. APPL.(S)	EXTENSION	TOTAL UNITS	EXTENSION	PERCENT COMPLETE
CHANGE (ORDER #6, ACC'T NO. 11230-85-140-11440	3											
-	COR-43 Loading dock soffit framing	1.00	Lump Sum	\$7,368.00		\$7,368.00	1.00	\$7,368.00	0.00	\$0.00	1.00	\$7,368.00	100.00%
-	COR-44 Exterior siding panel abatement	1.00	Lump Sum	\$12,927.00		\$12,927.00	1.00	\$12,927.00	0.00	\$0.00	1.00	\$12,927.00	100.00%
	COR-47 Extra electrical, security and communication wiring adds	1.00	Lump Sum	\$11,357.00		\$11,357.00	1.00	\$11,357.00	0.00	\$0.00	1.00	\$11,357.00	100.00%
	COR-48 Temp fuel piping for emergency generator	1.00	Lump Sum	\$2,836.00		\$2,836.00	1.00	\$2,836.00	0.00	\$0.00	1.00	\$2,836.00	100.00%
	COR-45 Underground fuel tank removal esting	1.00	Lump Sum	\$5,621.00		\$5,621.00	1.00	\$5,621.00	0.00	\$0.00	1.00	\$5,621.00	100.00%
	CHANGE ORDER #6 TOTAL					\$40,109.00		\$40,109.00	1	\$0.00	.	\$40,109.00	_
GRAND TO	OTALS (CONTRACT TOTALS PLUS CHANG	GE ORDERS)			\$10,023,945.30			\$480,209.00	•	\$7,166,049.38		\$7,646,258.38	- 76.28%