



EXISTING DWELLING SOUTH ELEVATION



EXISTING DWELLING WEST ELEVATION



LOCATION FOR PROPOSED CARRIAGE HOUSE



315 S. Mills St.
CONDITION EXAMPLES
FRONT PORCH



315 S. Mills St.
CONDITION EXAMPLES
EXTERNAL FOUNDATION WALL- SOUTH SIDE



**315 S. Mills St.
CONDITION EXAMPLES
FLOOR JOIST ROT AT FOUNDATION WALL**



**315 S. Mills St.
CONDITION EXAMPLES
FLOOR JOIST ROT AT FOUNDATION WALL**



**315 S. Mills St.
CONDITION EXAMPLES
IMPROPERLY SIZED WINDOW - NORTH SIDE**



**315 S. Mills St.
CONDITION EXAMPLES
MAIN BATHROOM**