A photograph of a room's interior, focusing on the ceiling and upper walls. A white ceiling fan with a light fixture is visible in the upper left. The ceiling is white and shows some signs of wear or discoloration. Below the ceiling, there are brown curtains covering a window. The walls are a light color, possibly off-white or light beige. The overall lighting is dim, suggesting an indoor setting at night or in low light.

622 HOWARD PLACE  
BUCKLED CEILING  
SETTLEMENT



622 HOWARD PLACE  
INTERIOR CRACKING  
SETTLEMENT

632 HOWARD PLACE  
BUCKLED WALL INTERIOR







622 HOWARD PLACE  
DIFFERENTIAL SETTLEMENT  
COLLAPSING PORCH STRUCTURE





622 HOWARD PLACE  
FOUNDATON SETTLEMENT  
WATER INFILTRATION





622 HOWARD PLACE



622 HOWARD PLACE  
INTERIOR WALL CRACKING  
STRUCTURAL MOVEMENT  
SETTLEMENT



632 HOWARD PLACE  
INTERIOR CRACKING  
SETTLEMENT






632 HOWARD PLACE  
INTERIOR WALL CRACKS  
SETTLEMENT






622 HOWARD PLACE  
FOUNDATION MOVEMENT  
SHORED FLOOR STRUCTURE





632 HOWARD PLACE  
FOUNDATION SETTLEMENT  
WATER DAMAGE

622 HOWARD PLACE  
UNEVEN FOUNDATION SETTLEMENT  
EXTERIOR WALL CRACKING









632 HOWARD PLACE  
BUCKLED CEILING AND WALL  
SETTLEMENT AND WATER  
DAMAGE

632 HOWARD PLACE  
BUMP OUT MOVEMENT  
UNEVEN SETTLEMENT





632 HOWARD PLACE  
EXTERIOR BUMP OUTS




632 HOWARD PLACE  
BUMP OUT FOUNDATION  
SETTLEMENT AND WATER  
DAMAGE





632 HOWARD PLACE  
FOUNDATION DAMAGE  
SETTLEMENT AND WATER  
INFILTRATION






632 HOWARD PLACE



632 HOWARD PLACE  
BUMP OUT UNEVEN FOUNDATION  
SETTLEMENT - FALLING AWAY FROM  
MAIN STRUCTURE




632 HOWARD PLACE  
INTERIOR HALLWAY






632 HOWARD PLACE  
INTERIOR ROOM





632 HOWARD PLACE  
WALL AND CEILING SETTLEMENT  
CRACKS - MOVEMENT






632 HOWARD PLACE  
INTERIOR WATER DAMAGE CEILING



632 HOWARD PLACE  
INTERIOR WATER DAMAGE





632 HOWARD  
WATER DAMAGE CEILING