

View from east looking west.



Side entry to home showing steps




No Access to bath for wheelchair



No Access in Kitchen or room to open stove



Poor head clearance to basement (narrow hall)



Garage and maple tree to be removed for new home



Rear of Home

