

# 1034 Walsh Road



South view of property from North side of Sycamore Road looking south, brush to be removed with building and fencing



View from corner of Sycamore Road and Walsh road, looking South West, 8' high damaged fence, building and small brush to be removed.



View of building from south, note boarded up garage door on right, small trees and overgrown weeds to be removed, concrete and asphalt to remain until future development per DNR closure letter requirements



# 1034 Walsh Road



Gravel cap to remain on west side of building, view from south, facing north towards Sycamore Road



Front entry curb cut, fenced gated entry, metal building to demo with damaged roof



Street view through storm damaged, graffiti target metal fence, to be removed