




View West between 120 & 124 North Hancock



View from the South West of 119, 123 & 125 North Butler



View from the North East (Rear) of 119, 123 & 125 N Butler



View from the South East (Rear) of 119, 123 & 125 North Butler

119, 123 & 125 North Butler Existing Exterior Conditions
May 7, 2007



View from North West



View from South West



View from North East



View from South East

119 North Butler Existing Exterior Conditions
May 7, 2007



Basement



First Floor Front LR



First Floor Front Unit Bath



First Floor Front Unit Kitchen



First Floor Rear Unit Kitchen




First Floor Rear Unit Bedroom



Front Stair



Second Floor Living Room



Second Floor Hall




Second Floor BR




Second Floor Kitchen



Second Floor Bath



View from North West



View from South West



View from North East



View from South East

123 North Butler Existing Exterior Conditions
May 7, 2007



Stair



East/Common Entry




Basement



South Unit Kitchen



South Unit Hall/Bedroom




South Unit Living Room



North Unit Living/Bed Room




North Unit Kitchen




South Unit Bedroom


123 North Butler Existing Interior Conditions
May 7, 2007



View from North West



View from South West



View from South West



View from North East



View from South East



View from South East

125 North Butler Existing Exterior Conditions
May 7, 2007



Basement




First Floor Kitchen




First Floor Hall/LR



First Floor Living Room




Second Floor Hall



Second Floor Kitchen



Second Floor Living Room



Third Floor Bedroom



Third Floor Hall



Stair Down to 2nd Floor



Second Floor Bedroom