

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213

Photo - 1

Front of Risk



Photo - 2

garage side



Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 3

heavy charring on front upper siding,
soffit



Photo - 4

rear of risk

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213

Photo - 5

dwelling side



Photo - 6

front-opposite view



Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 7

alleged point of origin



Photo - 8

garage roof opened by FD

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213




Photo - 9

smoke in garage, no structural damage except roof



Photo - 11

off kitchen/breakfast room-double door onto deck

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 10

kitchen/breakfast room area



Photo - 12

kitchen/breakfast room

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213



Photo - 13

living room



Photo - 14

living room-front door entry

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213



Photo - 15

living room ceiling



Photo - 16

living room to hallway

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213




Photo - 17

bedroom 1-door was closed-smoke damage, minor structural (finish sheetrock)




Photo - 18

smoke damage to clothes in bedroom 1

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213



Photo - 19

hallway



Photo - 20

rear office/game room

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 21

rear office/game room



Photo - 22

hardwood flooring-gameroom

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213



Photo - 23

bedroom 2



Photo - 24

bedroom 2

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213



Photo - 25

bedroom 2



Photo - 26

bathroom

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768
Policy # 264841951
Ins Claim # 66F318775-213



Photo - 27

bathroom



Photo - 28

stairway to finished basement-off
kitchen area

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 29

utility room-heavy smoke and water



Photo - 30

utility room

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 31

entry to family room-heavy smoke and water



Photo - 32

family room

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 33

pool room off family room



Photo - 34

floor in family room

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 35

master bedroom in basement



Photo - 36

clothing, water to carpeted floor,
paneling and ceiling wet

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 37

ceiling



Photo - 38

storage closet, water damage to paneling

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 39

storage in basement-contents
salvagable here



Photo - 40

bathroom in basement

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 41

ceiling in pool room



Photo - 42

rear deck charred

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 43

rear deck, siding, soffitt and fascia.
also, roof damage observed



Photo - 44

garage roof

Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213

Photo - 45

dwelling roof also opened



Photo - 46

heavy smoke around vents, chimney



Photo Sheet

Insured Nelson, Kari & Bradley

Coverage BLDG

Claim # 57614-30768

Policy # 264841951

Ins Claim # 66F318775-213



Photo - 47

close up