




Campus Drive entrance



Street level facade



Campus Drive facade




Parapet damage



Water damage due to leaking roof



Additional water damage from leaking roof



Water damage in TV lounge



Additional water damage



Typical apartment room



Apartment air conditioner




Typical apartment bathroom ceiling




Typical apartment kitchenette and refrigerator




Water damage in kitchenette



Hallway radiator



Fire damage in basement storage area



Telephone room