PLAT OF SURVEY

DESCRIPTION OF LINES SURVEYED: The southerly line of the most westerly portion and the westerly line of the most southerly portion of Lot 6, Certified Survey Map No. 103, recorded in Volume 1 of Certified Survey Maps on Page 103, formerly part of Outlot 114 of Burke Assessor's Plat No. 1, and located in the NW 1/4 of the NW 1/4 of Section 33, T8N, R10E, City of Madison, Dane County, Wisconsin



SURVEY REFERENCES:
1. CSM NO. 103
2. DAHLEN MAP NO. 543-A

SURVEYOR'S CERTIFICATE:
I, Ross A. Michaels, Wisconsin Registered Land Surveyor No. S-1696, hereby certify that I have surveyed the property lines described hereon and that the survey is correct to the best of my knowledge and belief.

Ross A. Michaels

Ross A. Michaels, Registered Land Surveyor, S-1696
SURVEYED: September 3, 2010

WISCONSIN
ROSS A. MICHAELS
S-1696
MIDDLETON
WI
LAND SURVEYOR
9/7/2010

LEGEND

- ● SOLID ROUND IRON ROD FOUND, DIAMETER SHOWN
- ⊙ IRON PIPE FOUND, OUTSIDE DIAMETER SHOWN
- ○ 3/4" X 18" REBAR SET WEIGHING 1.50 LB./FT.
- ( ) PREVIOUSLY RECORDED DIMENSION
- ━━━ PROPERTY LINE SURVEYED
- ——— ——— OTHER LOT OR RIGHT-OF-WAY LINES

SURVEYED FOR:
Vietus LLC
Attn: Robert Letzing
9 Mountain Ash Trail
Madison, WI 53717

Notbohm Michaels Surveying, Inc.
6314 Odana Road
Madison, WI 53719
(608) 277-0503

OFFICE MAP NO. 866 S