


ADJACENT HOUSE TO THE SOUTH
(218 S. Marquette St)




ADJACENT HOUSE TO THE NORTH
(210 S. Marquette St)




DAMAGED 2 UNIT
(214 S. Marquette St)



REAR YARD OF DAMAGED 2 UNIT
(214 S. Marquette St)



REAR ELEVATION OF DAMAGED 2 UNIT
(214 S. Marquette St)



HOUSE DIRECTLY ACROSS THE STREET
(213 S. Marquette St)

1 Exterior wall moved out @ top of Stairs
214 S Marquette Street




2 Interior NE corner wall separation @ 1st Floor
214 S Marquette Street






3 Uplift of Living Room floor
214 S Marquette Street



4 Wall movement @ 1st Floor Bathroom
214 S Marquette Street



5 Separation of header @ Bay Window
214 S Marquette Street



6 Broken Wall Stud & wall movement @ 1st Floor
214 S Marquette Street



7 Temporary Shoring & removed finishes @ 1st Floor
214 S Marquette Street



8 Remains of Kitchen @ 2nd Floor
214 S Marquette Street