

PHOTOS OF EXISTING SITE CONDITIONS:

KLINKE CLEANERS

MADISON, WI

PHOTOS:



SOUTHWEST ELEVATION



SOUTH ELEVATION



PARTIAL SOUTH ELEVATION




PARTIAL WEST ELEVATION




WEST ELEVATION



WEST ELEVATION



NORTH ELEVATION




NORTH ELEVATION




SOUTHEAST ELEVATION



EAST ELEVATION



EAST OF SITE
LOOKING SOUTH



WEST ELEVATION OF
EXISTING BLDG. TO REMAIN

PHOTOS OF EXISTING INTERIOR CONDITIONS:

KLINKE CLEANERS
MADISON, WI


PHOTOS:




EXISTING BLOCK WALL
TO REMAIN



SOUTH ELEVATION



TENANT TO BE DEMOLISHED



TENANT TO BE DEMOLISHED



PARTIAL LOWER LEVEL
TO BE DEMOLISHED



PARTIAL LOWER LEVEL
TO BE DEMOLISHED




PARTIAL LOWER LEVEL
TO BE DEMOLISHED




TENANT TO BE DEMOLISHED



STAIR TO PARTIAL
LOWER LEVEL



TENANT TO BE
DEMOLISHED



TENANT TO BE
DEMOLISHED



TENANT TO BE DEMOLISHED



TENANT TO BE DEMOLISHED