





Historical Photo

DELTA UPSILON  
CHAPTER HOUSE RENOVATION





Site Survey/Site Plan

# DELTA UPSILON

## CHAPTER HOUSE RENOVATION





Lakefront Setback Graphic

**DELTA UPSILON**  
CHAPTER HOUSE RENOVATION





Current Conditions - Exterior

DELTA UPSILON  
CHAPTER HOUSE RENOVATION






Current Conditions - Exterior

DELTA UPSILON  
CHAPTER HOUSE RENOVATION






Current Conditions - Windows

DELTA UPSILON  
CHAPTER HOUSE RENOVATION





Current Conditions - Front Entry

DELTA UPSILON  
CHAPTER HOUSE RENOVATION





Current Conditions - Exterior - Lakefront Facade

DELTA UPSILON  
CHAPTER HOUSE RENOVATION






Current Conditions - Exterior - Lakefront Facade

DELTA UPSILON  
CHAPTER HOUSE RENOVATION





Exterior Elevation - South and East

DELTA UPSILON  
CHAPTER HOUSE RENOVATION






Exterior Elevation - North and West


DELTA UPSILON  
CHAPTER HOUSE RENOVATION



1



2




Floor Plans

**DELTA UPSILON**  
CHAPTER HOUSE RENOVATION






3/4




5



**DELTA UPSILON**  
CHAPTER HOUSE RENOVATION

Floor Plans





Proposed Front Entry

DELTA UPSILON  
CHAPTER HOUSE RENOVATION






Proposed - Addition to First Floor Dining Room

DELTA UPSILON  
CHAPTER HOUSE RENOVATION






Historical and Current Conditions - Trophy Room

DELTA UPSILON  
CHAPTER HOUSE RENOVATION





Proposed Design - Trophy Room

DELTA UPSILON  
CHAPTER HOUSE RENOVATION





Proposed Design - Living Room

DELTA UPSILON  
CHAPTER HOUSE RENOVATION